




AG 4S-A22

English
עברית

1
17

1



2



3










4



5





10**11****12**

AG 4S-A22

en	Original operating instructions	1
he	הוראות הפעלה מקוריות	17

1 Information about the documentation

1.1 About this documentation

- Read this documentation before initial operation or use. This is a prerequisite for safe, trouble-free handling and use of the product.
- Observe the safety instructions and warnings in this documentation and on the product.
- Always keep the operating instructions with the product and make sure that the operating instructions are with the product when it is given to other persons.

1.2 Explanation of symbols used

1.2.1 Warnings

Warnings alert persons to hazards that occur when handling or using the product. The following signal words are used:



DANGER

DANGER !

- ▶ Draws attention to imminent danger that will lead to serious personal injury or fatality.



WARNING

WARNING !

- ▶ Draws attention to a potential threat of danger that can lead to serious injury or fatality.



CAUTION

CAUTION !

- ▶ Draws attention to a potentially dangerous situation that could lead to slight personal injury or damage to the equipment or other property.

1.2.2 Symbols in the documentation

The following symbols are used in this document:

	Read the operating instructions before use.
	Instructions for use and other useful information
	Dealing with recyclable materials
	Do not dispose of electric equipment and batteries as household waste

1.2.3 Symbols in the illustrations

The following symbols are used in illustrations:

2	These numbers refer to the corresponding illustrations found at the beginning of these operating instructions
3	The numbering reflects the sequence of operations shown in the illustrations and may deviate from the steps described in the text
(11)	Item reference numbers are used in the overview illustrations and refer to the numbers used in the product overview section
!	This symbol is intended to draw special attention to certain points when handling the product.

1.3 Product-dependent symbols

1.3.1 Symbols on the product

The following symbols are used on the product:



2223267

	Wear eye protection
n	Rated speed
/min	Revolutions per minute
RPM	Revolutions per minute
	Diameter
	Direct current (DC)
	The product supports wireless data transmission compatible with iOS and Android platforms.
Li-Ion	Li-ion battery
	Hilti Li-ion battery type series used. Observe the information given in the section headed Intended use .
	Never use the battery as a striking tool.
	Do not drop the battery. Never use a battery that has suffered an impact or is damaged in any other way.

1.4 Product information

HILTI products are designed for professional users and only trained, authorized personnel are permitted to operate, service and maintain the products. This personnel must be specifically informed about the possible hazards. The product and its ancillary equipment can present hazards if used incorrectly by untrained personnel or if used not in accordance with the intended use.

The type designation and serial number are printed on the rating plate.

- Write down the serial number in the table below. You will be required to state the product details when contacting Hilti Service or your local Hilti organization to inquire about the product.

Product information

Angle grinder	AG 4S-A22
Generation	01
Serial no.	

1.5 Declaration of conformity

We declare, on our sole responsibility, that the product described here complies with the applicable directives and standards. A copy of the declaration of conformity can be found at the end of this documentation.

The technical documentation is filed here:

Hilti Entwicklungsgesellschaft mbH | Tool Certification | Hiltistrasse 6 | 86916 Kaufering, Germany

2 Safety

2.1 Safety instructions

2.1.1 General power tool safety warnings

⚠ WARNING Read all safety warnings, instructions, illustrations and specifications provided with this power tool. Failure to follow all instructions listed below may result in electric shock, fire and/or serious injury.

Save all warnings and instructions for future reference.

The term "power tool" in the warnings refers to your mains-operated (corded) power tool or battery-operated (cordless) power tool.

Work area safety

- Keep work area clean and well lit. Cluttered or dark areas invite accidents.



- ▶ **Do not operate power tools in explosive atmospheres, such as in the presence of flammable liquids, gases or dust.** Power tools create sparks which may ignite the dust or fumes.
- ▶ **Keep children and bystanders away while operating a power tool.** Distractions can cause you to lose control.

Electrical safety

- ▶ **Power tool plugs must match the outlet. Never modify the plug in any way. Do not use any adapter plugs with earthed (grounded) power tools.** Unmodified plugs and matching outlets will reduce risk of electric shock.
- ▶ **Avoid body contact with earthed or grounded surfaces, such as pipes, radiators, ranges and refrigerators.** There is an increased risk of electric shock if your body is earthed or grounded.
- ▶ **Do not expose power tools to rain or wet conditions.** Water entering a power tool will increase the risk of electric shock.
- ▶ **Do not abuse the cord.** Never use the cord for carrying, pulling or unplugging the power tool. Keep cord away from heat, oil, sharp edges or moving parts. Damaged or entangled cords increase the risk of electric shock.
- ▶ **When operating a power tool outdoors, use an extension cord suitable for outdoor use.** Use of a cord suitable for outdoor use reduces the risk of electric shock.
- ▶ **If operating a power tool in a damp location is unavoidable, use a residual current device (RCD) protected supply.** Use of an RCD reduces the risk of electric shock.

Personal safety

- ▶ **Stay alert, watch what you are doing and use common sense when operating a power tool. Do not use a power tool while you are tired or under the influence of drugs, alcohol or medication.** A moment of inattention while operating power tools may result in serious personal injury.
- ▶ **Use personal protective equipment. Always wear eye protection.** Protective equipment such as a dust mask, non-skid safety shoes, hard hat or hearing protection used for appropriate conditions will reduce personal injuries.
- ▶ **Prevent unintentional starting.** Ensure the switch is in the off-position before connecting to power source and/or battery pack, picking up or carrying the tool. Carrying power tools with your finger on the switch or energising power tools that have the switch on invites accidents.
- ▶ **Remove any adjusting key or wrench before turning the power tool on.** A wrench or a key left attached to a rotating part of the power tool may result in personal injury.
- ▶ **Do not overreach.** Keep proper footing and balance at all times. This enables better control of the power tool in unexpected situations.
- ▶ **Dress properly. Do not wear loose clothing or jewellery. Keep your hair, clothing and gloves away from moving parts.** Loose clothes, jewellery or long hair can be caught in moving parts.
- ▶ **If devices are provided for the connection of dust extraction and collection facilities, ensure these are connected and properly used.** Use of dust collection can reduce dust-related hazards.
- ▶ **Do not let familiarity gained from frequent use of tools allow you to become complacent and ignore tool safety principles.** A careless action can cause severe injury within a fraction of a second.

Power tool use and care

- ▶ **Do not force the power tool. Use the correct power tool for your application.** The correct power tool will do the job better and safer at the rate for which it was designed.
- ▶ **Do not use the power tool if the switch does not turn it on and off.** Any power tool that cannot be controlled with the switch is dangerous and must be repaired.
- ▶ **Disconnect the plug from the power source and/or remove the battery pack, if detachable, from the power tool before making any adjustments, changing accessories, or storing power tools.** Such preventive safety measures reduce the risk of starting the power tool accidentally.
- ▶ **Store idle power tools out of the reach of children and do not allow persons unfamiliar with the power tool or these instructions to operate the power tool.** Power tools are dangerous in the hands of untrained users.
- ▶ **Maintain power tools and accessories.** Check for misalignment or binding of moving parts, breakage of parts and any other condition that may affect the power tool's operation. If damaged, have the power tool repaired before use. Many accidents are caused by poorly maintained power tools.
- ▶ **Keep cutting tools sharp and clean.** Properly maintained cutting tools with sharp cutting edges are less likely to bind and are easier to control.
- ▶ **Use the power tool, accessories and tool bits etc. in accordance with these instructions, taking into account the working conditions and the work to be performed.** Use of the power tool for operations different from those intended could result in a hazardous situation.



2223267

- **Keep handles and grasping surfaces dry, clean and free from oil and grease.** Slippery handles and grasping surfaces do not allow for safe handling and control of the tool in unexpected situations.

Battery tool use and care

- **Recharge only with the charger specified by the manufacturer.** A charger that is suitable for one type of battery pack may create a risk of fire when used with another battery pack.
- **Use power tools only with specifically designated battery packs.** Use of any other battery packs may create a risk of injury and fire.
- **When battery pack is not in use, keep it away from other metal objects, like paper clips, coins, keys, nails, screws or other small metal objects, that can make a connection from one terminal to another.** Shorting the battery terminals together may cause burns or a fire.
- **Under abusive conditions, liquid may be ejected from the battery; avoid contact.** If contact accidentally occurs, flush with water. If liquid contacts eyes, additionally seek medical help. Liquid ejected from the battery may cause irritation or burns.
- **Do not use a battery pack or tool that is damaged or modified.** Damaged or modified batteries may exhibit unpredictable behaviour resulting in fire, explosion or risk of injury.
- **Do not expose a battery pack or tool to fire or excessive temperature.** Exposure to fire or temperature above 130° C (265 °F) may cause explosion.
- **Follow all charging instructions and do not charge the battery pack or tool outside the temperature range specified in the instructions.** Charging improperly or at temperatures outside the specified range may damage the battery and increase the risk of fire.

Service

- **Have your power tool serviced by a qualified repair person using only identical replacement parts.** This will ensure that the safety of the power tool is maintained.
- **Never service damaged battery packs.** Service of battery packs should only be performed by the manufacturer or authorized service providers.

2.1.2 Safety warnings common for grinding, sanding, wire brushing, polishing or abrasive cutting-off operations:

- **This power tool is intended to function as a grinder, sander, wire brush or cut-off tool. Read all safety warnings, instructions, illustrations and specifications provided with this power tool.** Failure to follow all instructions listed below may result in electric shock, fire and/or serious injury.
- **Operations such as polishing are not recommended to be performed with this power tool.** Operations for which the power tool was not designed may create a hazard and cause personal injury.
- **Do not use accessories which are not specifically designed and recommended by the tool manufacturer.** Just because the accessory can be attached to your power tool, it does not assure safe operation.
- **The rated speed of the accessory must be at least equal to the maximum speed marked on the power tool.** Accessories running faster than their rated speed can break and fly apart.
- **The outside diameter and the thickness of your accessory must be within the capacity rating of your power tool.** Incorrectly sized accessories cannot be adequately guarded or controlled.
- **Threaded mounting of accessories must match the grinder spindle thread.** For accessories mounted by flanges, the arbour hole of the accessory must fit the locating diameter of the flange. Accessories that do not match the mounting hardware of the power tool will run out of balance, vibrate excessively and may cause loss of control.
- **Do not use a damaged accessory.** Before each use inspect the accessory such as abrasive wheels for chips and cracks, backing pad for cracks, tear or excess wear, wire brush for loose or cracked wires. If power tool or accessory is dropped, inspect for damage or install an undamaged accessory. After inspecting and installing an accessory, position yourself and bystanders away from the plane of the rotating accessory and run the power tool at maximum no-load speed for one minute. Damaged accessories will normally break apart during this test time.
- **Wear personal protective equipment.** Depending on application, use face shield, safety goggles or safety glasses. As appropriate, wear dust mask, hearing protectors, gloves and workshop apron capable of stopping small abrasive or workpiece fragments. The eye protection must be capable of stopping flying debris generated by various operations. The dust mask or respirator must be capable of filtrating particles generated by your operation. Prolonged exposure to high intensity noise may cause hearing loss.
- **Keep bystanders a safe distance away from work area.** Anyone entering the work area must wear personal protective equipment. Fragments of workpiece or of a broken accessory may fly away and cause injury beyond immediate area of operation.



- ▶ Hold the power tool by insulated gripping surfaces only, when performing an operation where the cutting tool may contact hidden wiring. Contact with a "live" wire will also make exposed metal parts of the power tool "live" and could give the operator an electric shock.
- ▶ Position the cord clear of the spinning accessory. If you lose control, the cord may be cut or snagged and your hand or arm may be pulled into the spinning accessory.
- ▶ Never lay the power tool down until the accessory has come to a complete stop. The spinning accessory may grab the surface and pull the power tool out of your control.
- ▶ Do not run the power tool while carrying it at your side. Accidental contact with the spinning accessory could snag your clothing, pulling the accessory into your body.
- ▶ Regularly clean the power tool's air vents. The motor's fan will draw the dust inside the housing and excessive accumulation of powdered metal may cause electrical hazards.
- ▶ Do not operate the power tool near flammable materials. Sparks could ignite these materials.
- ▶ Do not use accessories that require liquid coolants. Using water or other liquid coolants may result in electrocution or shock.

Kickback and related warnings

Kickback is a sudden reaction to a pinched or snagged rotating wheel, backing pad, brush or any other accessory. Pinching or snagging causes rapid stalling of the rotating accessory which in turn causes the uncontrolled power tool to be forced in the direction opposite of the accessory's rotation at the point of the binding.

For example, if an abrasive wheel is snagged or pinched by the workpiece, the edge of the wheel that is entering into the pinch point can dig into the surface of the material causing the wheel to climb out or kick out. The wheel may either jump toward or away from the operator, depending on direction of the wheel's movement at the point of pinching. Abrasive wheels may also break under these conditions.

Kickback is the result of power tool misuse and/or incorrect operating procedures or conditions and can be avoided by taking proper precautions as given below.

- ▶ Maintain a firm grip on the power tool and position your body and arm to allow you to resist kickback forces. Always use auxiliary handle, if provided, for maximum control over kickback or torque reaction during start-up. The operator can control torque reactions or kickback forces, if proper precautions are taken.
- ▶ Never place your hand near the rotating accessory. Accessory may kickback over your hand.
- ▶ Do not position your body in the area where power tool will move if kickback occurs. Kickback will propel the tool in direction opposite to the wheel's movement at the point of snagging.
- ▶ Use special care when working corners, sharp edges etc. Avoid bouncing and snagging the accessory. Corners, sharp edges or bouncing have a tendency to snag the rotating accessory and cause loss of control or kickback.
- ▶ Do not attach a saw chain woodcarving blade or toothed saw blade. Such blades create frequent kickback and loss of control.

Safety warnings specific for grinding and abrasive cutting-off operations:

- ▶ Use only wheel types that are recommended for your power tool and the specific guard designed for the selected wheel. Wheels for which the power tool was not designed cannot be adequately guarded and are unsafe.
- ▶ The grinding surface of centre depressed wheels must be mounted below the plane of the guard lip. An improperly mounted wheel that projects through the plane of the guard lip cannot be adequately protected.
- ▶ The guard must be securely attached to the power tool and positioned for maximum safety, so the least amount of wheel is exposed towards the operator. The guard helps to protect the operator from broken wheel fragments, accidental contact with wheel and sparks that could ignite clothing.
- ▶ Wheels must be used only for recommended applications. For example: do not grind with the side of cut-off wheel. Abrasive cut-off wheels are intended for peripheral grinding, side forces applied to these wheels may cause them to shatter.
- ▶ Always use undamaged wheel flanges that are of correct size and shape for your selected wheel. Proper wheel flanges support the wheel thus reducing the possibility of wheel breakage. Flanges for cut-off wheels may be different from grinding wheel flanges.
- ▶ Do not use worn down wheels from larger power tools. Wheel intended for larger power tool is not suitable for the higher speed of a smaller tool and may burst.

Additional safety warnings specific for abrasive cutting-off operations:

- ▶ Do not "jam" the cut-off wheel or apply excessive pressure. Do not attempt to make an excessive depth of cut. Overstressing the wheel increases the loading and susceptibility to twisting or binding of the wheel in the cut and the possibility of kickback or wheel breakage.



- ▶ **Do not position your body in line with and behind the rotating wheel.** When the wheel, at the point of operation, is moving away from your body, the possible kickback may propel the spinning wheel and the power tool directly at you.
- ▶ **When wheel is binding or when interrupting a cut for any reason, switch off the power tool and hold the power tool motionless until the wheel comes to a complete stop. Never attempt to remove the cut-off wheel from the cut while the wheel is in motion otherwise kickback may occur.** Investigate and take corrective action to eliminate the cause of wheel binding.
- ▶ **Do not restart the cutting operation in the workpiece. Let the wheel reach full speed and carefully re-enter the cut.** The wheel may bind, walk up or kickback if the power tool is restarted in the workpiece.
- ▶ **Support panels or any oversized workpiece to minimize the risk of wheel pinching and kickback.** Large workpieces tend to sag under their own weight. Supports must be placed under the workpiece near the line of cut and near the edge of the workpiece on both sides of the wheel.
- ▶ **Use extra caution when making a "pocket cut" into existing walls or other blind areas.** The protruding wheel may cut gas or water pipes, electrical wiring or objects that can cause kickback.

Safety warnings specific for sanding operations:

- ▶ **Do not use excessively oversized sanding disc paper. Follow manufacturers recommendations, when selecting sanding paper.** Larger sanding paper extending beyond the sanding pad presents a laceration hazard and may cause snagging, tearing of the disc or kickback.

Safety warnings specific for wire brushing operations:

- ▶ **Be aware that wire bristles are thrown by the brush even during ordinary operation. Do not overstress the wires by applying excessive load to the brush.** The wire bristles can easily penetrate light clothing and/or skin.
- ▶ **If the use of a guard is recommended for wire brushing, do not allow any interference of the wire wheel or brush with the guard.** Wire wheel or brush may expand in diameter due to work load and centrifugal forces.

2.1.3 Additional safety instructions

Personal safety

- ▶ Only use the product if it is in perfect working order.
- ▶ Never tamper with or modify the tool in any way.
- ▶ Avoid touching rotating parts – risk of injury!
- ▶ Wear protective gloves also when changing the accessory tool. Touching the accessory tool presents a risk of injury (cuts or burns).
- ▶ Before starting work, check the hazard class of the dust that will be produced when working. Use an industrial vacuum cleaner with an officially approved protection class in compliance with the locally applicable dust protection regulations. Dust from materials such as lead-based paint, certain types of wood and concrete/masonry/stone containing quartz, minerals or metal may be harmful to health.
- ▶ Make sure that the workplace is well ventilated and, where necessary, wear a respirator appropriate for the type of dust generated. Contact with or inhalation of the dust may cause allergic reactions and/or respiratory or other diseases among operators or bystanders. Certain kinds of dust are classified as carcinogenic such as oak and beech dust, especially in conjunction with additives for wood conditioning (chromate, wood preservative). Material containing asbestos may be handled only by specialists.
- ▶ Take breaks between working and do physical exercises to improve the blood circulation in your fingers. Exposure to vibration during long periods of work can lead to disorders of the blood vessels and nervous system in the fingers, hands and wrists.

Electrical safety

- ▶ Before beginning work, check the working area for concealed electric cables or gas and water pipes. External metal parts of the power tool may give you an electric shock if you damage an electric cable accidentally.

Using and handling power tools with care

- ▶ Do not use cutting discs for grinding.
- ▶ Tighten the accessory tool and flange securely. If the accessory tool and flange are not tightened securely, the accessory tool may work loose from the spindle due to the braking effect of the motor after switching off.
- ▶ Comply with the manufacturer's instructions for handling and storing grinding discs.

2.1.4 Battery use and care


- ▶ Observe the special regulations and instructions applicable to the transport, storage and use of Li-ion batteries.



- ▶ Do not expose batteries to high temperatures, direct sunlight or fire.
- ▶ Do not disassemble, crush or incinerate batteries and do not subject them to temperatures over 80 °C.
- ▶ Do not use or charge batteries that have suffered mechanical impact, have been dropped from a height or show signs of damage. In this case, always contact your **Hilti Service**.
- ▶ If the battery is too hot to touch it may be defective. In this case, place the product in a non-flammable location, well away from flammable materials, where it can be kept under observation and allowed to cool down. In this case, always contact your **Hilti Service**.

3 Description

3.1 Overview of the product 1



- | | |
|---|--|
| ① | Battery |
| ② | Battery release button |
| ③ | Charge state indicator |
| ④ | Speed regulation |
| ⑤ | On/off switch |
| ⑥ | Spindle lock button |
| ⑦ | Side handle |
| ⑧ | Guard release button |
| ⑨ | Spindle |
| ⑩ | Standard guard |
| ⑪ | Clamping flange with O-ring |
| ⑫ | Abrasive cutting disc / abrasive grinding disc |
| ⑬ | Clamping nut |
| ⑭ | Kwik lock clamping nut (optional) |
| ⑮ | Pin wrench |
| ⑯ | Dust filter |

3.2 Intended use

The product described is a hand-held cordless angle grinder. It is designed for cutting and grinding metal and mineral materials, brushing, sanding and for hole cutting in tiles, all without use of water. It can be used only for dry grinding / cutting.

- ▶ The power tool may be used for cutting, slitting and grinding mineral materials only when equipped with the corresponding guard (optional accessory).
- ▶ A dust removal hood together with a suitable **Hilti** vacuum cleaner must be used for working on mineral materials such as concrete or stone.
- ▶ Use only **Hilti** Li-ion batteries of the B 22 series with this product.
- ▶ Use only **Hilti** battery chargers of the C4/36 series for charging these batteries.

3.3 Items supplied

Angle grinder, side handle, standard guard, front cover, clamping flange, clamping nut, pin wrench, dust filter, operating instructions.

Other system products approved for use with this product can be found at your local **Hilti Store** or online at: www.hilti.group.



2223267

3.4 ATC

The power tool is equipped with the ATC (Active Torque Control) quick-acting electronic cut-out. If the accessory tool sticks or stalls, the power tool will suddenly pivot about its own axis in the opposite direction. ATC detects this sudden pivoting movement of the power tool and switches the tool off immediately.



For ATC to function correctly, the power tool must be free to pivot.

After an ATC cut-out, switch the power tool off and then on again.

3.5 Temperature-dependent motor protection

The temperature-dependent motor protection system monitors current input and motor temperature and thus prevents the power tool overheating.

If the motor is overloaded through application of excessive working pressure, the power tool's performance drops noticeably or it may stall completely.

If the power tool stalls or slows significantly due to overloading, release the pressure applied to the tool and then allow it to run under no load for approx. 30 seconds.

3.6 Guard with front cover

When grinding with straight grinding discs and cutting with cutting discs in metalworking applications, use the standard guard with front cover.

3.7 DC-EX 125/5" C compact dust hood for cutting (accessory)

When cutting mineral materials with diamond cutting discs, use the DC-EX 125/5" C compact hood.

Use of this guard for working on metal is not permissible.

3.8 DC-EX 125/5" M dust hood for grinding (accessory)

The power tool must be equipped with a dust hood when mineral materials are cut or slit with diamond cutting discs.

CAUTION Use of this hood for working on metal is prohibited.

3.9 DG-EX 125/5" dust hood for grinding (accessory)

The grinding system is suitable only for occasional use with diamond cup wheels for grinding mineral materials.

Use of this guard for working on metal is not permissible.

3.10 Li-ion battery charge status display

The charge status of the Li-ion battery is displayed after one of the two battery release buttons is pressed.

Status	Meaning
4 LEDs light.	Charge status: 75 % to 100 %
3 LEDs light.	Charge status: 50 % to 75 %
2 LEDs light.	Charge status: 25 % to 50 %
1 LED lights up.	Charge status: 10 % to 25 %
1 LED flashes.	Charge status: < 10 %



Indication of the charge status is not possible while the power tool is in operation or immediately after operation. If the battery charge status LEDs flash, please refer to the information given in the Troubleshooting section.

4 Consumables

Only synthetic resin-bonded, fiber-reinforced discs with maximum Ø 125 mm which are approved for use at a rotational speed of at least 11,000/min and a peripheral speed of 80 m/s may be used.

The maximum permissible grinding disc thickness is 6.4 mm and the maximum cutting disc thickness is 3.0 mm.



ATTENTION! When cutting or slitting with abrasive cutting discs always use the standard guard with the additional front cover, or a fully enclosing dust hood.

Discs

Type	Application	Designation	Material
Abrasive cutting disc	Cutting, slitting	AC-D	Metal
Diamond cutting disc	Cutting, slitting	DC-TP, DC-D (SPX, SP, P)	Mineral
Abrasive grinding disc	Rough grinding	AG-D, AF-D, AN-D	Metal
Diamond grinding disc	Rough grinding	DG-CW (SPX, SP, P)	Mineral
Wire brushes	Wire brushes	3CS, 4CS, 3SS, 4SS	Metal
Diamond core bit	Drilling in tiles	DD-M14	Mineral
Abrasive resin-fiber disc	Rough grinding	AP-D	Metal

Suitability of discs for the equipment used

Item	Equipment	AC-D	AG-D, AF-D, AN-D	DG-CW (SPX, SP, P)	DC-TP, DC-D (SPX, SP, P)	AP-D	3CS, 4CS, 3SS, 4SS, DD-M14
A	Guard	X	X	X	X	X	X
B	Front cover (in combination with A)	X	—	—	X	—	—
C	Dust hood (grinding) DG-EX 125/5"	—	—	X	—	—	—
D	Dust hood (cutting) DC-EX 125/5°C (in combination with A)	—	—	—	X	—	—
E	DC-EX 125/5" M dust hood for slitting	—	—	—	X	—	—
F	DC-EX SL adapter (in combination with E)	—	—	—	X	—	—
G	Side handle	X	X	X	X	X	X
H	Clamping nut	X	X	X	X	—	—
I	Clamping flange	X	X	X	X	—	—
J	Kwik lock (optional instead of H)	X	X	—	X	—	—
K	Clamping nut for abrasive resin-fiber disc	—	—	—	—	X	—
L	Support plate	—	—	—	—	X	—

5 Technical data

	AG 4S-A22-125
Rated voltage	21.6 V
Rated speed	8,500 /min
Maximum disc diameter	125 mm
Weight in accordance with EPTA procedure 01	3.1 kg
Drive spindle thread	M14
Spindle length	22 mm



2223267

	AG 4S-A22-125
Ambient temperature for operation	-17 °C ... 60 °C
Storage temperature	-20 °C ... 70 °C

5.1 Technical data

Spindle length	22 mm
Ambient temperature for operation	-17 °C ... 60 °C
Storage temperature	-20 °C ... 70 °C

5.2 Battery

Battery operating voltage	21.6 V
Ambient temperature for operation	-17 °C ... 60 °C
Storage temperature	-20 °C ... 40 °C
Battery charging starting temperature	-10 °C ... 45 °C

5.3 Noise information and vibration values in accordance with EN 60745

The sound pressure and vibration values given in these instructions have been measured in accordance with a standardized test and may be used to compare one power tool with another. They may be used for a preliminary assessment of exposure.

The data given represents the main applications of the power tool. However, if the power tool is used for different applications, with different accessory tools or is poorly maintained, the data may vary. This may significantly increase exposure over the total working period.

An accurate estimation of exposure should also take into account the times when the power tool is switched off, or when it is running but not actually being used for a job. This may significantly reduce exposure over the total working period.

Identify additional safety measures to protect the operator from the effects of noise and/or vibration, for example: Maintaining the power tool and accessory tools, keeping the hands warm, organization of work patterns.

AG 4S-A22-125

Noise information

Emission sound pressure level (L_{pA})	81.5 dB(A)
Uncertainty for the sound pressure level (K_{pA})	3 dB(A)
Sound power level (L_{WA})	92.5 dB(A)
Uncertainty for the sound power level (K_{WA})	3 dB(A)

Vibration information

Other applications, such as cutting, may produce vibration values that deviate from the given values.

Surface grinding with the vibration-absorbing side handle ($a_{h,AG}$)	4.7 m/s ²
Sanding with sandpaper with the vibration-absorbing side handle ($a_{h,DS}$)	5.3 m/s ²
Uncertainty (K)	1.5 m/s ²

6 Before use

6.1 Charging the battery

1. Before charging the battery, read the operating instructions for the charger.
2. Make sure that the contacts on the battery and the contacts on the charger are clean and dry.
3. Use an approved charger to charge the battery.



6.2 Inserting the battery

⚠ CAUTION

Risk of injury by short circuit or falling battery!

- ▶ Before inserting the battery, make sure that the contacts on the battery and the contacts on the product are free of foreign matter.
- ▶ Make sure that the battery always engages correctly.

1. Charge the battery fully before using it for the first time.
2. Push the battery into the battery holder until it engages with an audible click.
3. Check that the battery is seated securely.

6.3 Removing the battery

1. Press the battery release buttons.
2. Remove the battery from the tool.

6.4 Fitting the side handle

- ▶ Screw the side handle into one of the threaded bushings provided.

6.5 Fitting or removing the guard

⚠ CAUTION

Risk of injury. The accessory tool may be hot or have sharp edges.

- ▶ Wear protective gloves when fitting, removing or adjusting the accessory tool or other parts and when troubleshooting.

- ▶ Observe the instructions for fitting the applicable guard.

6.5.1 Installing standard guard



The guard is equipped with locating lugs that ensure only guards of a type suitable for use with the power tool can be fitted. The locating lugs of the guard fit into the guard mount on the power tool.

1. Fit the guard onto the drive spindle collar so that the two triangular marks on the guard and on the power tool are in alignment.
2. Press the guard onto the drive spindle collar.
3. Press the guard release button and then rotate the guard until it engages in the desired position.
→ The guard release button jumps back.

6.5.2 Adjusting standard guard

- ▶ Press the guard release button and then rotate the guard until it engages in the desired position.

6.5.3 Removing standard guard

1. Press the guard release button and then rotate the guard until the triangular marks on the guard and the power tool are in alignment.
2. Remove the guard.

6.6 Fitting or removing the front cover



The front cover, when used, is clipped onto the guard.

1. Position the front cover with the closed side on the standard guard and push it on until it engages.
2. To remove it, release the catch for the front cover and then lift the front cover away from the standard guard.



2223267

6.7 Fitting and removing accessory tools

WARNING

Risk of injury. The accessory tool may work loose due to the braking effect of the motor.

- ▶ Wait until the accessory tool has come to a standstill before touching or gripping the accessory tool or the clamping nut.
- ▶ Secure the accessory tool by tightening the clamping flange and clamping nut firmly so that no parts work loose from the spindle due to the braking effect of the motor.

CAUTION

Risk of injury. The accessory tool may be hot.

- ▶ Wear protective gloves when changing the accessory tool.

 Diamond discs must be replaced when their cutting or grinding performance drops significantly. This generally is the case when the segments reach a height of less than 2 mm.

Other discs must be replaced when their cutting performance drops significantly or other parts of the angle grinder (not the disc) come into contact with the material you are working on.

Abrasive discs must be replaced when their expiry date has been reached.

6.7.1 Fitting an accessory tool

1. Remove the battery. → page 11
2. Check that the O-ring is in place in the clamping flange and that it is undamaged.

Result

The O-ring is damaged.

There is no O-ring in the clamping flange.

- ▶ Fit a new clamping flange with O-ring.

3. Fit the clamping flange onto the drive spindle (keyed fit to prevent slipping/rotation).
4. Fit the accessory tool.
5. Screw on the clamping nut corresponding to the type of accessory tool fitted.
6. Press the spindle lockbutton and hold it in this position.
7. Use the pin wrench to tighten the clamping nut securely, then release the spindle lockbutton and remove the wrench.

6.7.2 Removing the accessory tool

1. Remove the battery. → page 11

CAUTION

Risk of breakage and irreparable damage. If the spindle lockbutton is pressed while the spindle is rotating, the accessory tool can detach from the power tool.

- ▶ Press the spindle lockbutton only when the spindle has stopped rotating.

2. Press the spindle lockbutton and hold it in this position.
3. Release the clamping nut by gripping it with the wrench and turning the nut counterclockwise.
4. Release the spindle lockbutton and remove the accessory tool.

6.7.3 Fitting an accessory tool secured with a **Kwik lock** nut

CAUTION

Risk of breakage. Heavy wear (abrasion) may cause the **Kwik lock** nut to break.

- ▶ When working with the power tool, make sure that the **Kwik lock** nut doesn't come into contact with the working surface.
- ▶ Do not use a damaged **Kwik lock** nut.

 The optional **Kwik lock** nut can be used instead of the standard clamping nut. Accessory tools (discs etc.) can then be changed without need for additional tools (keyless system).

1. Remove the battery. → page 11



- Check that the O-ring is in place in the clamping flange and that it is undamaged.

Result

The O-ring is damaged.

There is no O-ring in the clamping flange.

- Fit a new clamping flange with O-ring.

- Clean the clamping flange and the quick-release clamping nut.

- Fit the clamping flange onto the drive spindle.

- Fit the accessory tool.

- Screw on the **Kwik lock** nut until it is seated against the accessory tool.

- The name **Kwik lock** should be visible when the nut is screwed on.

- Press the spindle lock button and hold it in this position.

- Turn the accessory tool firmly by hand in a clockwise direction until the **Kwik lock** nut is tightened securely and then release the spindle lock button.

6.7.4 Removing an accessory tool secured with a Kwik lock nut

- Remove the battery. → page 11

⚠ CAUTION

Risk of breakage and irreparable damage. If the spindle lockbutton is pressed while the spindle is rotating, the accessory tool can detach from the power tool.

- Press the spindle lockbutton only when the spindle has stopped rotating.

- Press the spindle lockbutton and hold it in this position.

- Release the **Kwik lock** nut by turning it counterclockwise by hand.

- If the **Kwik lock** nut cannot be released by turning it by hand, use a pin wrench to turn the nut in a counterclockwise direction.



Never use a pipe wrench! A pipe wrench could damage the **Kwik lock** nut.

- Release the spindle lockbutton and remove the accessory tool.

6.7.5 Fitting the core bit 10

- Remove the battery. → page 11
- Fit the side handle. → page 11
- Install the standard guard.
- Place the core bit in position and tighten it hand-tight.
- Press and hold down the spindle lock button.
- Tighten the core bit with a suitable open-end wrench.
- Then release the spindle lock button and remove the open-end wrench.

6.7.6 Fitting the wire brush 11

- Remove the battery. → page 11
- Fit the side handle. → page 11
- Install the standard guard.
- Place the wire brush in position and tighten it hand-tight.
- Press and hold down the spindle lock button.
- Tighten the wire brush with a suitable open-end wrench.
- Then release the spindle lock button and remove the open-end wrench.

6.7.7 Fitting the abrasive resin-fiber disc 12

- Remove the battery. → page 11
- Fit the side handle. → page 11
- Install the standard guard.
- Fit the support plate and the abrasive resin-fiber disc, screw on the clamping nut and tighten it securely.
- Press the spindle lock button and hold it in this position.
- Use the pin wrench to tighten the clamping nut.
- Release the spindle lock button and remove the pin wrench.



2223267

7 Operation

7.1 Switching on

1. Press the rear section of the on/off switch.
2. Slide the on/off switch forward.
 - ↳ The motor runs.
3. Lock the on/off switch.

7.2 Grinding

CAUTION

Risk of injury. The accessory tool may suddenly stick or stall.

- Use the power tool with the side handle fitted and always hold it securely with both hands.

7.3 Cutting

- When cutting, apply moderate feed pressure and do not tilt the power tool or the cutting disc (when working, hold at approx. 90° to the surface being cut).



For best results when cutting profiles and square tube, start cutting at the smallest cross section.

7.4 Rough grinding

CAUTION

Risk of injury. The abrasive cutting disc could shatter and flying fragments may cause injury.

- Never use abrasive cutting discs for grinding.

- Move the power tool to and fro while maintaining a 5° to 30° angle of attack and applying moderate pressure.
 - ↳ This will avoid overheating and discoloration of the workpiece and help ensure an even surface finish.

7.5 Switching off

- Press the rear section of the on/off switch.
 - ↳ The on/off switch jumps into the off position and the motor stops.

8 Care and maintenance

WARNING

Risk of injury with battery inserted !

- Always remove the battery before carrying out care and maintenance tasks!

Care and maintenance of the tool

- Carefully remove any dirt that may be adhering to parts.
- Remove the dust filter and clean it and the air vents carefully, using a dry brush.
- Use only a slightly damp cloth to clean the casing. Do not use cleaning agents containing silicone as these can attack the plastic parts.

Care of the lithium-ion batteries

- Keep the battery free from oil and grease.
- Use only a slightly damp cloth to clean the casing. Do not use cleaning agents containing silicone as these may attack the plastic parts.
- Avoid ingress of moisture.

Maintenance

- Check all visible parts and controls for signs of damage at regular intervals and make sure that they all function correctly.
- Do not operate the product if signs of damage are found or if parts malfunction. Have it repaired immediately by **Hilti** Service.



- After cleaning and maintenance, fit all guards or protective devices and check that they function correctly.

i To help ensure safe and reliable operation, use only genuine Hilti spare parts and consumables. Spare parts, consumables and accessories approved by Hilti for use with the product can be found at your local **Hilti Store** or online at: www.hilti.group.

9 Transport and storage of cordless tools

Transport

⚠ CAUTION

Accidental starting during transport!

- Always transport your products with the batteries removed!
- Remove the battery.
- Never transport batteries in bulk form (loose, unprotected).
- Check the tool and batteries for damage before use after long periods of transport.

Storage

⚠ CAUTION

Accidental damage caused by defective or leaking batteries !

- Always store your products with the batteries removed!
- Store the tool and batteries in a place that is as cool and dry as possible.
- Never store batteries in direct sunlight, on heating units or behind a window pane.
- Store the tool and batteries in a place where they cannot be accessed by children or unauthorized persons.
- Check the tool and batteries for damage before use after long periods of storage.

10 Troubleshooting

If the trouble you are experiencing is not listed in this table or you are unable to remedy the problem by yourself, please contact **Hilti Service**.

10.1 Troubleshooting

Trouble or fault	Possible cause	Action to be taken
The battery runs down more quickly than usual.	Very low ambient temperature.	▶ Allow the battery to warm up slowly to room temperature.
The battery doesn't engage with an audible click.	The retaining lugs on the battery are dirty.	▶ Clean the retaining lugs and refit the battery.
1 LED flashes. The device does not work.	Low battery.	▶ Change the battery and charge the empty battery.
	The battery is too hot or too cold.	▶ Allow the battery to cool down or warm up slowly to room temperature.
All 4 LEDs flash. The device does not work.	The tool has been overloaded.	▶ Release the control switch and then press it again. Then allow the power tool to run under no load for approx. 30 seconds.
The angle grinder or battery gets very hot.	Electrical fault	▶ Switch the power tool off immediately, remove the battery, keep it under observation, allow it to cool down and contact Hilti Service .
The tool does not achieve full power.	A battery with inadequate capacity was used.	▶ Use a battery with adequate capacity.
The motor has no braking effect.	Low battery.	▶ Change the battery and charge the empty battery.



2223267

Trouble or fault	Possible cause	Action to be taken
The motor has no braking effect.	The power tool was overloaded briefly.	► Switch the power tool off and then on again.

11 RoHS (Restriction of Hazardous Substances)

Click on the link to go to the table of hazardous substances: qr.hilti.com/r9884540.
There is a link to the RoHS table, in the form of a QR code, at the end of this document.

12 Disposal

 Most of the materials from which **Hilti** tools and appliances are manufactured can be recycled. The materials must be correctly separated before they can be recycled. In many countries, your old tools, machines or appliances can be returned to **Hilti** for recycling. Ask **Hilti** Service or your Hilti representative for further information.

Battery disposal

Improper disposal of batteries can result in health hazards from leaking gases or fluids.

- DO NOT send batteries through the mail!
- Cover the terminals with a non-conductive material (such as electrical tape) to prevent short circuiting.
- Dispose of your battery out of the reach of children.
- Dispose of the battery at your **Hilti Store**, or consult your local governmental garbage disposal or public health and safety resources for disposal instructions.



- Do not dispose of power tools, electronic equipment or batteries as household waste!

13 Manufacturer's warranty

- Please contact your local **Hilti** representative if you have questions about the warranty conditions.



1.1 על אוחdot תיעוד זה

- קרא את תיעוד זה במלואו לפני השימוש הראשון. רק כך ניתן להבטיח עבודה בטוחה ונטולת תקלות.
- צית להואות בטיחות ואזהרות שבTİיעוד זה ועליה הatzיות על המוצר.
- שמרו את הוראות וההפעלה תמיד במצבו המקורי, והקפיד להעביר אותן לאדם שאליו אתה מעביר את המוצר.

1.2 הסבר הסימנים**1.2.1 אזהרות**

הזהירות מזכירה מפעלים מסכניים בשימוש במוצר. במודרך זה מופיעות מילוט המפתח הבאונות:



מצינית סכנה מיידית, המובילת לפציעות גוף קשות או מוות.



מצינת סכנה אפשרית, שיכולה להוביל לפצעות גוף קשות או מוות.



מצינת מצב שעלול להיות מסוכן ולהוביל לפצעות גוף קשות או למכדים לרכיש.

1.2.2 סמלים במסמך זה

הסמלים הבאים מופיעים בתיעוד זה:



קרא את הוראות הפעלה לפני השימוש



הנחיות לשימוש ו מידע שימושי נוספים



טיפול נכון בחומרים למייחזר



אין להשליך לפסולת הביתיית מכשירים חשמליים וסוללות

1.2.3 סמלים הבאים באירועים

הסמלים הבאים משמשים באירועים:



מספרים אלה מפנהים לאירוע המתאים בתחילת חוברת ההוראות



המספרים באירועים משקפים את רצף הפעולות, והם עשויים להיות שונים מרכז הפעולות המצוינות בטקסט



מספר הפריטים מופיעים באירוע **סקירה** ותואמים את המספרים במקרה בפרק **סקירת המוצר**



סימן זה אמור לעורר את תשומת לך המוחדר בעת השימוש במוצר.

1.3 סמלים ספציפיים לדגם המוצר**1.3.1 סמלים על המוצר**

הסמלים הבאים מופיעים על המוצר:



השתמש במוגבי עיניים



סל"ד נקוב



סיבובים ל/ה

/min



2223267

סיבובים לדקה	RPM
קוטר	
דרך ישיר	
המוצר תומך בתעבורת נתונים אלחוטית, המותאמת לשימוש עם פלטפורמות OS iOS ו-Android.	
סוללה ליתיום-יון	Li-Ion
סדרת דגמי סוללות ליתיום-יון של Hilti בשימוש. שם לב לננתונים בפרק שימוש בהתאם ליעוד .	
עלולם אין להשתמש בסוללה כפתיש.	
אין להפעיל את הסוללה. אין להשתמש בסוללה שנחכבה או שבייזוקה באופן אחר.	

1.4 פרטיו הכספי

HILTI מיעדים למשתמש המתקען, ווק אבטים מורשים, שערובו הקשר מתאימה, ראשאים לתפקידם. אבטים אלה חווים ללמידה באופן מיוחד את הסכנות האפשריות. המוצר המתואיר והעדירים שלו עלולים להיות מוכנים לתגובהם. כאשר אבטים אלה נבדקו בקשר לתהnia מסוימים בהם הם שאל בהתאם לייעוד.

תבונת המוציא	
AG 4S-A22	משחזת דזות
01	דור
	קס' סידורי

האגרת מאיטום 1.5

ההיעדר הטכני שמור כאן; החרת התאימות.

Hilti Entwicklungsgesellschaft mbH | Zulassung Geräte | Hiltistraße 6 | 86916 Kaufering, Germany

2

הוראות בטיחות 2.1

2.1.1 הוראות בטיחות כליליות לכל יחודה חשמלית
אזהרה קרא את כל ההוראות בטיחות, ההנחיות, האירורים והנתוניים הטכניים המצורפים לכל יחודה החשמלי. אי ציית להנחיות עלול להוביל להתחששות, לשרפה / או לפיציעות קשות.
שמור את כל ההוראות בטיחות וההנחיות לעיון בעתיד.

המונח "כל עבודה חשמלי" המשמש בהוראות הבתיוחות מתייחס לכל עבודה חשמלית המחויבים לרשף החשמל עם כל חשמל) או לכל עבודה חשמלית המופעלים באמצעות סוללה בטענת (לא כולל חשמל).

▪ שמר על אזור העבודה שלך בקי ודאג לתאורה מספקת. חוסר סדר או תאורה לקויה במקום העבודה עלולים לגרום בטיחות במקום העבודה

- **הראק' לדיים ואנכים** אחרים מכל היעבה החשמלי במחלק השימוש בו. אם דעתך תוסס אתה עלול לאבד את השילטה כל יעבה חשמלניים יצירם ניצוצות, שלולם להציג את האבק או אדים.
- **לאגאותו:** לאגאותו את כל היעבה החשמלי בסביבה שקיימת בה סכתן פיזיון או שישבם בה גדים או אבק דליקים.

五〇〇

בשוחות בחשמל ← הטענה היא שבלבוב החשמל חיבר לתאנים לשען החשמל. אסורה לשכנות בשום אופן את תקע החשמל. אל תשתמש בשען מותאם ביחיד עם כל בעודה חשמליים הקיימים הגנת הארץ. שימוש בתקעים חשמליים שלא עברו אישור ישובי חושך מקרים רבים בהם קיימת אמת בטענה להתקומש עליה.



- מגע מגע של הגוף בשטחים מוארים כגון צינורות, גופי חימום, תכורות ומרקרים. קיימת סכנה גבואה להתחשפות כאשר הגוף שליך מוארך.
- הרוק כלי העבודה חשמליים מגשם או רטיבות. חידרת מים לכל העבודות החשמליים מגדילה את הסיכון להתחשפות.
- אל תשמש בכבלי החשמל למטרות שלא לשם זה ועוד, לדוגמה: אל תרים את כלי העבודה החשמלי באמצעותם ואל תנסה לנתק את התקע משקע המשיכת הכבלי, הרוק את הכבלי החשמלי באמצעותם, שמן, פיכת חודה או חלקים נעימים. ככלים שעמידה ושותפהם בתלקים אරמים או גלאלים את הסיכון להתחשפות.
- כאשר אתה עבד עם כל העבודה החשמלי בחווץ, השטחן וק' בכבל מאריך מיותר לשימוש חיצוני. שימוש בכבלי מאריך המהאים לשימוש חיצוני מחייב את הסיכון להתחשפות.
- אם לא ניתן להימנע משימוש בכל העבודה החשמלי בסביבה לחיה, השטחן במעטפת פחת. השימוש בממפרט פחת מחייב את הסיכון להתחשפות.

ביטחונות של אבכים

- היה ערבי, שים לב מה שאתה עושה, ופעל בתובונה כאשר אתה עובד עם כל עבודה חשמלי. אל תעשייל כל עבודה חשמלית כאשרה עירף או מתחת השפעת סמים, אלכוהול או טרופות. די ברגע אחד של חוסר תשומת-לב בדעתו השימוש בכל העבודה החשמלי יוביל לוגדים מצטנויות קשות.
- לבש תמיד מיגון ומשקפי מגן. לביש ציוד מגן אישי, כגון מסכת אבק, בעלי בטיחות מונעות החלקה, קסדות מגן וכן מגני שמיעה – בהתאם לסוג השימוש כבלי העבודה החשמלי – מקטינה את הסיכון לפציעות.
- מנע הפעלה בשוגג. דו שכליל העבודה החשמלי יוביל לפחותה שאמה מחבר אותו לאספקת החשמל ו/או לפci שאטהה מחבר את הסוללה לפני הרכבת. אל תניח את אכבעך על המתוך בדעתו נושא את המכשיר וול תחבר אותו לאספקת החשמל כאשר הוא מופעל, אחריה עלולות להיגרם תאונות.
- הרחק כל כוכו ומאנו מפתחות ברירים לפני שאמה מפעלי את כל העבודה החשמלי. כל עבודה או מפתחות הנמצאים בקרבת חלקים מסתובבים עלולים לגרום פציעות.
- הימנע מתכונותות גוף לא נוכנות. עמוד באופן יציב ושמור תמיד על שווי משקל. כך תוכל לשולט טוב יותר בכל העבודה החשמלי במסיבים לא צפויים.
- לבש בגדים מוחאים. תלבש בגדים וחיבים או תכשיטים. הרחק את השער, הבגדים וככפות מחלקים נעים. בגדים רופפים, תכשיטים ושיער ארוך עלולים להתvipס בחלקים נעים.
- כאשר ניתן להתקין התקי שאייבת אבק ולידיה יש לוודא שהם מחוברים לחשמל, ויש להקפיד להשטחן בהם בקרה. שיווין שהתקין שאיבת אבק מקטין את הסוכנות הנוגעת מהאבק.
- אל תהי שאנך בונשאי בבחירה ועל התעלם מஹאות בטיחות של כל עבודה חשמליים, גם אם שהשתמשה במכשיר פעמיים הרבה ואתה מכיר אותו היטב. התנהגות רשלית עלולה להוביל לפציעות קשות בגין שגיון.

שימוש וטיפול בכל העבודה החשמלי

- אל תעשייל עופס רב מדי על המכשיר. השטחן בכל העבודה החשמלי המתאים לעבודה שאמה מבצע. כל העבודה החשמלי המהאים בפטין לך עבודה טוגה ובזבוז יורה בתהום ההפיק הקוקב.
- אל תשמש בכל העבודה אם המתג שלו איבן תקין. כל עבודה חשמלי שלא ניתן להפעיל או לכבות אותו מהוועה סכנה ווש לתנקן.
- נתק את תקע החשמל מהSKU ו/או הסר את הסוללה לפני שאמה מבצע כובונים במכשיר, מחלף כלים או לאחר שאמה מפסקס בעודם עם המכשיר. אמצע דזרירות זה מונע הפעלה בשוגג של כל העבודה החשמלי.
- שמור כל עבודה חשמליים שאינם בשימוש הרחק מהישג ידים של ילדים. אל תאפשר לאנשים שאיבם יודעים כיצד להשתמש במכשיר או שלא קראו את הוראות להשתמש במכשיר. כל עבודה חשמליים הם מוסכנים כאשר משתמשים בהם אשייסי סחרי ביטין.
- טפל בכל העבודה שבירום ואביזרים בהקפה. בזוק אם החלקים הנעים פועלם בצוואר חלה ואינם נתקעים, אם ישן חלקים שבירום או מקלקלים המשבשים את הפעולה התקינה של כל העבודה החשמלי. לפני השימוש במכשיר דאג לתיקון חלקים אל-קניים. תאוות בורו בעקבות עירום התקינה להזעה של כל עבודה חשמלי.
- שמור על כל החיתוך חזים ונכיקים. כל חיתוך מוטפלים היטב, שלhalbיהם חדים נתקעים פחות וקלים יותר לתפעול.
- השתמש רק בכל העבודה החשמלי, באביזרים, בכל העבודה החשמליים וכן הלהה בהתאם להוואות אלה. הרחשה בתנאי העבודה ובפעלה שלילך לבצע. שימוש בכל העבודה החשמליים מושם ומרגד. ידית ואזרוי אחזיה חלקים אינם מאפרים תפעול בטוח.

שימוש וטיפול בכל עבודה בטיענים

- טען את הסוללות ורק במטיענים שהומלכו על ידי היוצרן. טעינה של סוללה במתען המיעוד לטעינה של סוללות מסווג אחר עלולות לגרום לשרפפה.
- השתמש לשם רק בסוללות המתאימות לכל העבודה החשמלי. שימוש בסוללות אחרות עלול לגרום לשרפפה.
- שמור סוללות שאינן בשימוש הרחק ממהדק הייר מושדרים, ממטבעות, מפתחות, מספרים, ברגים או חפצים מותכניים קטנים אחרים שיכולים להשבר בין המעלים. קרא בין גגיהם הסוללה עלול לרום לכיווית או לשרפפה.
- שימוש שחי עלול לגרום לדיליפ נזדים מוטוללה. אל תגע בנחלים אלה. אם נגע בהם במרקחה, שטוף את האזור במים. אם ההורן נוגע בעיניים, פנה לרופא. נחל סוללות שדילף עלול לגרום לגירויים בעור ולוכויות.
- אין להשתמש בסוללה שנזנחה או שבזקתה. סוללות שנזנכו או שננרכו בהן שנייניהם עשויים לגרום לא כאביה בצוואר ולגרום לשרפפה, לפיצוץ ולפצעות.
- אין לחשוף סוללות לאש או לטמפרטורות גבוהות. אש או טמפרטורות גבוהות מ-130°C (265°F) עלולות לגרום לפיצוץ.



2223267

צית לכל הנקודות הנוגעות לטעינה, וכך פעם אל תען את הסוללה או את הכל' עם הסוללה בסביבה שהטמפרטורה בה נמצאת מוחץ לטווח הפיצין בהוראות הפעולה. טעינה שגوية או טעינה בטמפרטורה שבמציאות מוחץ לטווח הפיצין בהוראות הפעולה עלולה להרים את הסוללה ולהגביר את הסיכון לשרפה.

שירות

- דאג לתיקון כל העבודה החשמלי שלך ורק בידי טכניים מוסמכים, המשמשים בחוקי חילוף מקוריים בלבד. כך תבטיח שמייה על בטיחות העבודה במקשיך.
- אל לטפל בעצמך בסוללות שכזאתו. רק היצרן או מublicה מורשית מטעמו רשאים לטפל בסוללות.

- 2.1.2 הנחיות בטיחות מסוותות לעבודות השחזה, ליטוש עם ביר ליטוש, עבודה עם מרשות ברטל, הברקה וחיתוך:
 - כל העבודה החשמלי זו מועד לשימושו ממשחתה, מלשתת פיר ליטוש, מברשת ברטל ומוכנות יתרון. שום לב ללו החזיות הבטיחות, ההירות, האירום והנכונות יתוקן. אם התעלם מהנחיות הבאות, התוצאה עלולה להיות התחשמלות ו/או פיציעות קשות.
 - מכשיר חשמלי זה אינו מתאים לעבודות הברקה. שימוש במקשיך שלא למטרה שלשמה הוא ייעד מהווע סכנה ועלול לגרום לפיציעות.
 - אין להשתמש באביזרים שלא אושרו והומלצו על ידי היצרן במועד לשימוש בכל עבודה חשמלי זה. העבודה שאפשר לחבר את האביזר לכלי העבודה החשמלי אינה מבטיחה שהשימוש בו יהיה בטוח.
 - מהירות הנטזוב המותרת של הכל' המחבר חייבות להיות גובנת לפחות כmo המהירות המרבית המצוינת על כל העבודה החשמלי. כל מחוור שסמותנו מהר מוחור עולל להשרר ולהירקך בחלל.
 - הקוטר החיצוני והעובי של הכל' המחבר חייבים להתאים לנדרושים לדרישות כל' העבודה שלך. אביזרים בממדות לא מתאימות עלולים להיות לא מוגנים מספיק או לעובוד ללא שליטה.
 - כלים בעלי חיבור עם תכירג חייבים לאחאים בזיקן לתוכר החשמלית של האגן, כלים אשנים מוחורו או רוחם בזורה. כלים הדורשים התקינה באמצעות החשמלי ישתובבו בזורה לא חלקה, ירעוד חזק מזקק והטבורה עלול לאבדן שליטה על כל' העבודה.
 - אין להשתמש בכלים פגומים. לפחות מבחן קדקוק או בדיקת דיסק השחזה בעץ בדיקה לאירועים וסודקים, שחקה או בלאי מוגבה, בדיקת מברשות ברטל לאירועי וויי ברטל שושוררים וושבררים. אם כל' העבודה או האביזר נזקק בזקק אם נזקקו או השמשת במקום זאת באביזר שלא נזקק. לאחר שבדקה את הכל' וחויראת אותן, הרחק עצמן ואנשיים הנמצאים בקרבת מקום אל מוחץ למשור התגוננה של כל' המסתובב, ואפשר למקשיך לעובוד דקה שלמה במהירות מרבית. אביזרים פגומים יישורו בזקק בודק כל' בשמש דקה בדיקת הבדיקה.
 - לבש ציד מגן איש. השטמש – בהתאם לסוג העבודה – במשמעותו יגן או בגין פגמים מלא. לבש מסכת אבק, מגני שמייה, כפפות מגן או סיר מיזה שגן עליך פיפוי חלקיי חומר – בהתאם לצורך. יש להגן על עיניים מפני גופים זרים שעפים בחלל, כפי שעולל להתרחש בעבודות מסוימות. מסכת אבק ומסכת הנשימה צויקות לסנן שונוצר במהלך השימוש. חסיפה ממושכת לרעש חזק עלולה לגרום פגיעה בשmissה.
 - ואשאנשים אחרים עוזמים ברוחק בזווית אחוריו העבודה. כל מי שמכנס לאזור העבודה חייב ללבוש ציד מגן איש. חלקים הנשברים מהחומר שבעבודה או שברים מהאביזר עלולים לההעוף בחלל ולגרום לפיציעות גם מוחץ לאזור העבודה הימני.
 - כאשר מבצעים עבודות שבחן הכל' עלל לפגוע בקווי החשמלי מוסתרים יש לאחד בכל' העבודה החשמלי רק במקרים מהחיה המבודדים. מעג בקווים המוליכים דרום עלול להעירר דרום גם לחלקים מתחכימים במקשיך שלך ולגרום להתחשמלאות.
 - הרחק את הכל' החשמלי מוסתרים. אם TABRD את השטיטה במקשיך עלול כל' החשמל להיחר או להיתפס, וכך הדודע שלך עלול לחתוך בגוף.
 - לעומת זאת כל' העבודה החשמלי לפני שהכל' המחבר נעצה. כל' מסתובב עשוי להיתקל במשטח שעליו הוא מונח, ובעקבות זאת כל' העבודה החשמלי עלול לנען לא שליטה.
 - אל אפשר ליל' העבודה החשמלי לפעול אם אין מחקק אותו. הגדים שלך עלולים להיתפס בכל' המסתובב, ובעקבות זאת הכל' עלול לחתוך בגוף.
 - כקה בגופו של אבק מתקני מהווע סכנת חשמלית.
 - אין להשתמש בכל' העבודה החשמלי בקרבת חומרם לדלקים. ביצוצות עלולים להציג אותן.
 - אין להשתמש באביזרים הדורשים חומרי קירור נוזלים. שימוש בהם או בחומר קירור נוזלים אחרים עלול לגרום להתחשמלאות.

רתע והבוחות מתקימות

- רתע הוא תגובה פתאומית עקב התקינות או חסימה של כל' מסתובב, כגון דיסק השחזה, דיסק ליטוש, מברשת ברטל וכן הלאה. התקינות או חסימה ובוילם לעצירה פתאומית של הכל' המסתובב. עקב כך אין כל' העבודה החשמלי, אם אין נמצאת בשטיטה, לכיוון המונע מהווע סכנתם.
- casar להזגמה דיסק השחזה נזקק או חומר שבבעודה, העצה של דיסק שונן לחומר עשויל להיליך שם וכן גורם לפריצת הדיסק או לרתע. הדיסק יינע כתע לכיוון הסובב של הדיסק בזקק החסימה.
- רתע נוצר כתוצאה משימוש שאגי בכל' העבודה החשמלי. ניתן למגע אוטו בערתת אמצעי זהירות המוסברים להלן.
- החדק את הכל' העבודה החשמלי באופן יציב והבא את גזע וזרועותך לתנוחה שבה תוכל לספוג רתע. השתמש תמיד בדירת האידה הנוספת, אם קיימת, כדי שתהייה לך שטיטה גודלה מוגבהת – בהתאם לכיוון הסובב של הדיסק בזקק החסימה.
 - בעת האצת המקשיך. המשמשים יכול לשוטט בכוחות הרתע והותגובה אם יתקוטר אמצעי זהירות מתקאים.



- **עלול אל תקבר אתיך לצלוי מוסטובב.** הכליל עלול לנוע מעל היד של במקורה של רתען.
 - **דאג שגופך לא ימצא** בתחום שלכיוונו כל העבודה החשמלי יונע ממקורה של רתען. הרתע מושך את כל העבודה החשמלי לכיוון התכוונה של הדיסק במרקם ססמייה.
 - **היה חזר במייחד בעבודה בפינות,** על **כחות חדים** וכן **להלא.** מען מצב שבו הכליל ננדף מהחומר בעבודה או נתקע בו. בפינות, בכזותם חדים או כאשר הכליל מנדף הוא נזונה להזיז. זה גורם לבבן שליטה או לרתען.
 - **אין להשתמש בלבד** בשירות או בלבד ביחסו משוכן. כולם כאלה גורמים לעתים קרובות לרתען או לאבדן השליטה בכליה. העבודה החשמלי.

הנחיות בטיחות מיוחדות להשחזה וחיתוך:

הכחות ביחס לנופשות מיוחדות לחימור:

- מבחן חסימה של דיסק החיתוך ואל תפעיל כוח לחיצה רב. אל תבצע חתכים עמוקים. עומס יתר על דיסק החיתוך מוגבר את הסיכון להתקעתו או לחסימה ובכך את הטיסון לתרע או לשבירת כל החשכה.
 - אל תתקרב לאזור שלפניו ומאחריו הדיסק המסתובב. במקרה של רתע כאשר דיסק החיתוך מסתובב חלק שבובודה, כי העובדה החשמלי עלול להידרך במכהו ולבזבז כוחון בירוד עם הדיסק.
 - אם דיסק החיתוך מתקע או אם אתה מפסיק לעטוף, כבה את המקשר והדחק אותו ציב עד שהדיסק נעצר למשך. לעומת זאת תנסה למשוך דיסק החיתוך מהחריצן בדמן שהוא עדין מסתובב, אחרת עלול להתרחש רתע. ברור מה היא הסיבה להתקענות וטפל בה.
 - אל תפעיל מחדש את כל העבודה החשמלי כל עוד הוא נמצא בתוך החלק שבובודה. אפשר לדיסק החיתוך להציג למחריות הסיבוב המורבית לפני שתמשיך בהירותה. אחר עלול הדיסק להתיתקע, להידרך אל מתחן חלק או לגרום לרתע.
 - להתכוופת תחת משקלם. יש לתמוך את החלק משני הצדדים של הדיסק, גם בקרבת מקום החיתוך וגם בקצה החלק.
 - היא דירה במודיע בחיתוך "טיסט" בקרות קיימים או בחלקים דומים. כאשר הדיסק חורז ופוגע בצענת גת, מים או חשמל או גזירות אדירות הוא עלול לבלוטו להרים.

הpecificities unique to Litosh's adaptations

- אין להשתמש בכירויות ליטוש גחלים דוד, אלא בכירויות המתחייבים בתוכו המחייבים של היצרן. נירות ליטוש הבולטים מעבר לדיסק עלולים לגרום לפציעות וכון לחםינה ולקרעה של ניר הליטוש וכן לרתען.
 - הנחיות בטיחות מיוחדות לעבורה עם מרשות ברחל:
 - שים לב מרבשות הבודבם מגדרות סיבי תיל גם במהלך שימוש רגיל. אין להפעיל עומס מופurd על סיבי התיל. סיבי תיל מתעויפים ככלים בודדים בחלקם בין הגדרים ותוך חוריו.
 - כאשר מומלץ להתקין מנגנון דיסק, שמנכו מעג בעין בין הדיסק לטסי התייל של המברשת. הקוטר של דיסקים שטוחים וגמויים ישוו לדילוי עבוגנות הפעלתם לעצם וכוחם אנטריפוגלי.

2.1.3 הוראות בטיחות נוספות

בטיוחת של אכשיס

- השתמש בוחרך בתנאי שהוא נמצא במצב טכני מושלם.
 - אל תבצע בשום אופן מיפויளיזיט או שינויים במכשיר.
 - אין לגעת בחקלים מסתובבים – סכת פצעיה!
 - לבש כפפות בטיחות גמ בעת החילפת כל. מגע כליל לזרים לפציעות ולכוויות.
 - בדוק לפחות את תקינות הוחן הבוגעתו של אבך החומר שבו תעבוד. השתמש בשואב אבך מקטיע בעל דירוג הגנה מסויש, התואם את המPLICות קורוז וטירילרים כןו מתחכמת עלולים להידק בראיות.
 - בטון / קירות / אבכים המPLICות קורוז וטירילרים כןו מתחכמת עלולים להידק בראיות.
 - dag לאירועו טוב במקום העובדה, ובמקרה הצורך לברוט לאירועו אלרגיות / או למלחת בכלי הנשימה של האבך לסתו האבך שבו אתה עובד. נגיעה בסוגי אבך אלה או שיפתח עליה לרום לאירועו אלרגיות / או למלחת בכלי הנשימה של האבך לשונו האבך מושלם.



0000063

בקורת מקום. סוג אבק מסוימים, כגון אבק של אבן או בוק, חשבים סטטניים, במיוחד בשילוב עם חומרים אחרים המשמשים לטיפול בעץ (כרוםט, חומר הגנה לעץ). רק מומחים רשאים לעבוד בחומרים המכילים אבסטן. ערך הפסוקות לעבודה ומוגלים לשיפור דמיון הדם לאבעוט. הרזידנס מהמקשר שוויון לאחר עבודה מושכת לגורם להפערות בכלי הדם או במערכת העצמים של האבעוט, כפות הידיים או שורשי כף היד.

ביטחות בחשמל

- לפני תחילת העבודה יש לבדוק אם שםם כבלי חשמל, צינורות גז או מים נסתרים. חלקים מתכתיים חיוניים במקשר יכולם לגרום להנוגעים בקווים חשמל.

טיפול ושימוש קפדיים בכלי עבודה חשמל


- אין להשתמש בדיסקי חימר לצורך השחזה.
- הדק את הכלים ואת האוגן. אם הכלים והאוגן לא הוקו כראוי, יתכן כי לאחר כיבוי המකשר יתנתק הכלים מהזרע עקב בלימת המוגע.
- שם לב להנחיות הייצן בנוגע לטיפול ולאחסון של דיסקי השחזה.

2.1.4 טיפול ושימוש קפדיים בסוללות נטענות

- ציבור לתקנות הנוגעות להובלה, אחסון והפעלה של סוללות נטענות מסוג ליתיום-יון.
- הרחק את הסוללות ממקומות חמים מוד, מקרית שימוש ישירה ומאש.
- אין לפוך, למטון, לחמס לטמפרטורה גבוהה מ- 80°C או לשורף את הסוללות הטענות.
- אין להשתמש ולטעון סוללות שב毛病, שנפלו מגובה גבוהה מפמר או שנזקקו באופן אחר. במקרה זה יש ליזור קשר עם השירות של Hilti.
- אם הסוללה תהה כל כך שהיא ניכנת בה, יתכן שהיא אינה תקינה. העמד את המזח במקום לא דליק במרקם מספיק מחומר דליקים, כך שתוכל להציג עלי הסוללה, ואפשר לה להתקrho. במקרה זה יש ליצור קשר עם השירות של Hilti.

3.1 תיאור סקירת המוצר

①	סוללה
②	לחוץ שחרור סוללה
③	חיוי רמת טעינה
④	ויסות מהירות
⑤	מתג הפעלה/ביבי
⑥	לחוץ נעילת ציר
⑦	דית אחיזה צידית
⑧	לחוץ שחרור מגן הדיק
⑨	ציר
⑩	מגן דיסק סטנדרטי
⑪	אוגן נגדי עם טבעת O
⑫	דיסק חותם / דיסק השחזה
⑬	אום היזוק
⑭	אום היזוק מהיר Kwik lock (אופציונלית)
⑮	מפתח
⑯	מסנן אבק



3.2 שימוש בהתאם ליעוד

- המוצר המתואר זו משחת דזות ינית המופעלת באמצעות סוללה בטענת. היא מיועדת לעבודות חיטוך והשחזה של חומרים מתכתיים ומיינרליים, להפרשה, ליטוש באמצעות כיריך לטוחן ולקידוז בארכיטים – ללא שימוש בפימס. מותר להשתמש בה/חיתוך/השחזה בשים בלבד.
- כאשר משתמשים במachinery הדזותית לחיתוך, חיטוך והשחזה של חומרים מיינרליים כובה להשתמש במגן דיסק מתאים (רכישה בתכף).
 - כאשר 用户ים בחומרים מיינרליים כגון בטון או אבן ממולץ להשתמש במגן שאייה המותאם לשואב אבק של **Hilti**.
 - השימוש עבור מוצר זה רק בסוללות ליתיוםIon של **Hilti** מסדרת הגדמים B 22.
 - השימוש עבור מוצר זה רק במטענים של **Hilti** מהסדרה C4/36.

3.3 מפרט אספקה

משחת דזות ינית אチידה צדית, מגן דיסק סטנדרטי, כסוי קדמי, אוגן גגדי, אום הייזוק, מפתח, מסנן אבק, הווארות הפעלה. מוצרים נוספים המאושרים עבור המוצר שlk תמצאו **Hilti Store** או באינטרנט בכתובת: www.hilti.group.

ATC 3.4

המכ舍יר מצויד בפקנציה כיבוי אקלטורי מהיר ATC (Active Torque Control). אם הכל המכ舍יר נהסם או נתקע, המכ舍יר יתחל לסתובון בפאתומטי בזורה לא מבוקרת לכיוון הפהון. ATC מזהה את תנועת הסיבוב הפאתומטית והו מפסיק ומכבה מיד את המכ舍יר.

לצורך תפיקוד תקין המכ舍יר צריך להיות מסוגל להסתובב.
לאחר הכיבוי מהיר, כבה את המכ舍יר והפעל אותו מחדש.

**3.5 הגנה תלויות-טמפרטורה**

הגנה המונעת תלויות-טמפרטורה מפעחת על צירית החשמל וכן על טמפרטורת המגע ומגביה על המכ舍יר מפני התתחומות יתרה. כאשר ישנו עומס יתר על המגע עקב הפעלת כוח לחיצה חזק מאד, הספק המכ舍יר יפחית משמעותית וייתכן אפילו ייפלו שהוא יעצר. גם עקב עומס יתר המכסה נבער או שמהירות הסביבה שלו פוחתת, עליך להפחית את העומס על המכ舍יר ולהמשיך להפעלה אוthon במקבץ סרק במשך כ-30 דקות.

3.6 מגן דיסק עם כסוי קדמי 2

לצורך השחזה באמצעות דיסק' חיטוך ולצורך חיתוך באמצעות דיסק' חיתוך בעבודה בחומרים מתכתיים יש להשתמש במגן דיסק סטנדרטי הכלול כסוי קדמי.

3.7 מגן שאיבת אבק (חיתוך) C "5"-DC-EX 125/5 DC-EX 125/5" (אבייזר)

בעבודות חיתוך של חומרים מיינרליים באמצעות דיסק' חיתוך יילום יש להשתמש במגן הדיסק הקומפקטי C "5"-DC-EX 125/5. אסור לעבד מתחcit עם מגן דיסק זה.

3.8 מגן שאיבת אבק (חירוץ) M "5"-DC-EX 125/5 DC-EX 125/5" (אבייזר)

מותר לבצע עבודות חיטוך וחירוץ בחומרים מיינרליים באמצעות דיסק' חיתוך יילום רק עם מגן שאיבת אבק. דזרירות אסור לעבד מתחcit עם מגן דיסק זה.

3.9 מגן שאיבת אבק (השחזה) DG-EX 125/5 DG-EX 125/5" (אבייזר)

מערכת ההשחזה מיועדת ליטוש מזדקן של חומרים מיינרליים באמצעות דיסק' חיתוך יילום קעורים. אסור לעבד מתחcit עם מגן דיסק זה.

3.10 חיוי רמת טעינה של סוללת הליטיום-יון.

לאחר לחיצה על אחד משבci החזרו של הסוללה תציג רמת הטעינה של סוללת הליטיום-יון.

מספר	машמעות
4	נוריות מאירות.
3	נוריות מאירות.
2	נוריות מאירות.
1	נורית מאירה.



2223267

מצב	משמעות
נורית 1 מהבהבת.	רמת טעינה: > 10%

במהלך העבודה ומיד לאחר סיום לא ניתן לבדוק את רמת הטיענה של הסוללה. אם חיוי רמת הטיענה מהבהבת, ראה בבקשתו ההוראות בפרק פתרון תקלות.



4 חומרים מתחכמים

מותר להשתמש רק בדיסקי פיבר מחזקים עם חומר מקשר שurf סינטטי Ø 125 מ"מ, שאושרו לעבודות במהירות סיבוב של לפחות 11000 סל"ד ובמהירות היפר של 80 מ"/שנ'.

עובי דיסק החשודה המותר הוא 6.4 מ"מ ועובי דיסק החיתוך המKeySpecים מיל המותר הוא 0.3 מ"מ.

שים לבן **לזכור חיתוך וחירוץ באמצעות דיסק חיתוך יש להשתמש תמיד בмагן דיסק סטנדרטי עם כיסוי קדמי נוספים או במאן שאיבת אבק שלם סגור.**

דיסקים

דגם	חומר לעיבוד	קוד	שימוש	חומר
דיסק השחודה-חיתוך	מתכת'י	AC-D	חיתוך, חירוץ	
דיסק חיתוך יהלום	מינרלי	DC-TP, DC-D (SPX, SP, P)	חיתוך, חירוץ	
דיסק השחודה ליטוש	מתכת'י	AG-D, AF-D, AN-D	השחודה	
דיסק השחודה יהלום	מינרלי	DG-CW (SPX, SP, P)	השחודה	
מברשת פלדה	מתכת'י	3CS, 4CS, 3SS, 4SS	مبرשות פלדה	
מchod כוס יהלום	מינרלי	DD-M14	מקדח לאורחים	
דיסק פיבר	מתכת'י	AP-D	השחודה	

התאמת הדיסקים לסוג העבודה

פריט	ציד'	AC-D	,AG-D ,AF-D AN-D	DG-CW (SP,SPX) (P)	DC-TP DC-D (SP ,SPX) (P)	AP-D	,4CS ,3CS ,4SS ,3SS DD-M14
א	מגן דיסק	X	X	X	X	X	
ב	כיסוי קדמי (בשילוב עם א')	—	—	—	—	—	
ג	מגן שאיבת אבק (חשודה) DG-EX 125/5"	—	—	X	—	—	
ד	מגן שאיבת אבק (חיתוך) DC-EX 125/5" C (בשילוב עם א')	—	—	—	—	—	
ה	מגן שאיבת אבק (חיתוך) DC-EX 125/5" M	—	—	—	—	—	
ו	מתאים SL (בשילוב עם ה')	—	—	—	—	—	
ז	דיזית אחורית צוית	X	X	X	X	X	X
ח	אום הידוק	—	X	X	X	—	X
ט	אוגן נגד'	—	X	X	X	—	X
י	Kwik lock (אופציוני) ל-ה'	—	X	—	X	X	—
כ	אום הידוק עבור דיסק פיבר	X	—	—	—	—	—
ל	צלחת	X	—	—	—	—	—



AG 4S-A22-125	
מתח נקוב	21.6 וולט
סיל"ד נקוב	8,500 סיל"ד
קוטר דיסק מרבי	125 מ"מ
משקל בהתאם להיליך 01 EPTA	3.1 ק"ג
תברייג ציר הבעה	M14
אורך ציר	22 מ"מ
טמפרטורת סביבה בעבודה	60 °C ... -17 °C
טמפרטורת אחסון	70 °C ... -20 °C

5.1 נתוניים טכניים

5.1 נתוניים טכניים	
אורך ציר	22 מ"מ
טמפרטורת סביבה בעבודה	60 °C ... -17 °C
טמפרטורת אחסון	70 °C ... -20 °C

5.2 סוללה

מתח בעבודה עם סוללה בטענת	21.6 וולט
טמפרטורת סביבה בעבודה	60 °C ... -17 °C
טמפרטורת אחסון	40 °C ... -20 °C
טמפרטורת הסוללה בתחילת הטיענה	45 °C ... -10 °C

5.3 ערכי רעש לפי EN 60745

ערכי לחץ הקול והרעידות המצוינים בהוראות אלה נקבעו בהתאם לבוהל המודידה התקני, ובוון להשתמש בהם לצורך השוואתה בין כל עבודה שמשליל. הם מתייחסים גם להערכת דמיית של הנזקים.

הנתונים המצוינים תקפים לשימושים העיקריים בכלי העבודה החשמלי. אולם אם משתמשים בכלי העבודה החשמלי לשימושים אחרים, למשל אביזרים אחרים או אם המכשיר אינו עבר תחזוקה מספקת, הנתונים עשויים לשחזרו. בעקבות זאת פרטת העומסים למשך זמן העבודה כולה, עשוייה להיות גבוהה באופן משמעותי.

לצורך הערכה מדוייקת של העומסים יש ללקחת בחשבון גם את הדימויים שב們 המכשיר כבוי או שביהם הוא פועל אך אכן בשימוש בפועל. בעקבות זאת פרטת העומסים למשך זמן העבודה יכולה להיות נמוכה באופן משמעותי.

יש לבלעב בנסיבות בטיחות נספוחות להגנה על המסתמש מפני התשפעות של קווים או רעדות, כגון: תחזקה של כלי העבודה החשמלי ושל כלי העבודה הממחברים, שמירה על ידיים חמורות, ארוגן תחלי'י העבודה.

AG 4S-A22-125
מידע על רעשים

רמת לחץ קול (L_p)	81.5 dB(A)
אי-זוזאות רמת לחץ קול (K_p)	3 dB(A)
רמת הספק קול (L_{WA})	92.5 dB(A)
אי-זוזאות ברמת הספק הקול (K_{WA})	3 dB(A)

מידע על רעדות

שימושים אחרים, כגון חיתוך, עשויים לגרום לערכי רעדות אחרים.

ליטוש פבי שטוח עם ידיית מפחיתה רעדות ($a_{h,AG}$)	4.7 מ"ש ²
ליטוש באמצעות ביר ליטוש עם ידיית מפחיתה רעדות ($a_{h,DS}$)	5.3 מ"ש ²
אי-זוזאות (K)	1.5 מ"ש ²

6 הפעלה ראשונה

6.1 טיעינת סוללה

1. קרא את הוראות הפעלה של המטען לפני הטיענה.
2. זוד מה מגעים של הסוללה ושל המטען בקיים ויבשים.



2223267

עברית

25

3. טען את הסוללה במתען מאושר.

6.2 חיבור הסוללה

זהירות

- ██ סכנת פגיעה עקב קצר או נפילת סוללה!
- ████ לפி חיבור הסוללהaza ש망גים של הסוללה ושל המוצר נקיים מגופים זרים.
- ████ וא תמי שסתוללה תפופה היבשה.

1. טען את הסוללה לUMBר למטרו לפבי השימוש הראשוני.
2. הכנס את סוללה למחזיר ובמכך עד שתאותה שומע אוטה נגעת.
3. וא שסתוללה יושבת היבש.

6.3 הסרת הסוללה

1. לחץ על לחצני השחרור של הסוללה.
2. הסר את סוללה מהמכך.

6.4 התקנת ידיית האחיזה הצדית

- ████ הברג את ידיית האחיזה הצדית לאחד מהתבניות המיעדים לכך.

6.5 התקנה או הסרה של מגן הדיסק

זהירות

- ██ סכנת פגיעה. הכליל עשוי להיות חמ מואוד או חד.
- ████ לבש כפפות מגן בעת ביצוע עבודות התקנה, פירוק, כונון ותיקון תקלות.
- ████ שים לב להוראות התקנה של מגן הדיסק.

6.5.1 התקנת מגן דיסק סטנדרטי

- i** █ מגן הדיסק מצויד בידי התאמה, המבטיחים כי ניתן לחבר למכך רק מגן דיסק סותאים. מגן הדיסק בע ביחד עם ידייה ההתחממה בתושבת מגן הדיסק של המכך.

1. מוקם את מגן הדיסק על צוואר הציר כך שני הסימונים המשולשים, במגן ובמכך, יימצאו זה מול זה.
 2. דחף את מגן הדיסק על צוואר הציר.
 3. לחץ על לחצן שחרור המגן וסובב את מגן הדיסק למיקום הרצוי עד שהוא נגען.
- ⇨ כפתור שחרור המגן קופץ בחרדרה.

6.5.2 כונון מגן דיסק סטנדרטי

- ████ לחץ על לחצן שחרור המגן וסובב את מגן הדיסק למיקום הרצוי עד שהוא נגען.

6.5.3 הסרת מגן דיסק סטנדרטי

1. לחץ על לחצן שחרור המגן וסובב את מגן הדיסק עד שני הסימונים המשולשים, על מגן הדיסק ועל המכך, נמצאים זה מול זה.
2. הסר את מגן הדיסק.

6.6 התקנה או הסרה של הכיטוי הקדמי

- i** █ כאשר עובדים עם מגן קדמי יש לחבר אותו על מגן הדיסק.

1. לחבר את המגן הקדמי על מגן הדיסק הסטנדרטי עד שהוא נגען.
2. כדי להסיר אותו יש לפתח את הנעילה של המגן הקדמי ולהסיר אותו מגן הדיסק הסטנדרטי.



⚠️ אזהרה

- סכנת פגיעה. בעת בלימת מנוע המכשור עלול הכליל המחבר להתקתק.
- המטען עד שהכליל המחבר נעצר ורק אחד באום הגדי או באום היידק.
- הדק את הכליל ואית האוון הנגדי בעדר האום בミידא כדו שבעת בלימה המונע לא ישחררו חלקים.

⚠️ דANGER

- סכנת פגיעה. הכליל עלול להיות חם מאוד.
- לבש כפפות מגן בעת החלפת כליל.



יש להחליף דיסקי הילום ברגע שהספק החיתוך/ההשזה פוחת באופן ניכר. בדרך כלל זה מתרחש כאשר גובה סגןוני הילום מנוון מ-2 מ"מ.

סוגי דיסק אחרים יש להחליף ברגע שהספק החיתוך פוחת באופן ניכר או אם במהלך העבודה נוצר מעג בין חלקים של משחתת הדיזל (בלבד הידיסק) לבין החומר שבגעודה.

דיסק יליוטוש יש להחליף כשמייגר תאריר התגובה שלהם.

6.7.1 התקנת כליל

1. הסר את הסוללה. ← עמוד 26
2. ואט בטבעת ה-O נמצאת באונג הנגדי ושיהיא תקינה לगמור.

תוצאה

- טבעת O אינה תקינה.
- אין טבעת O באונג הנגדי.
- חבר אונג נגיד חדש עם טבעת O.
- 3. חבר את האונג הנגדי לציר המשחצתך שלא יסתובב.
- 4. חבר את האבידה.
- 5. הברג את אום היידק בהתאם לכליל העבודה שבשימוש.
- 6. לחץ על לחוץ נעילת הציר והחזק אותו לחוץ.
- 7. הדק את אום היידק בעדרת המפתח ולאחר מכן שחרר את לחוץ נעילת הציר והסר את המפתח.

6.7.2 הסרת כליל

1. הסר את הסוללה. ← עמוד 26

⚠️ דANGER

- סכנת שבירה והרס. לחיצה על לחוץ נעילת הציר רק כאשר הציר אכן מסתווב.
- לחוץ על לחוץ נעילת הציר והחזק אותו לחוץ.

2. לחוץ על לחוץ נעילת הציר והחזק אותו לחוץ.
3. חבר את פמחה האומרים וסובב אותו נגד כיוון השעון כדי לשחרר את אום היידק מהביר.
4. שחרר את לחוץ נעילת הציר והוציא את הכליל.

6.7.3 התקנה של כליל עם אום היידק מהיר Kwik lock**⚠️ דANGER**

- סכנת שבירה. עקב שחיקה מרווחה עללא אום היידק מהיר **Kwik lock** להישבר.
- וזה שבמהלך העבודה לא נוצרו מגע בין אום היידק מהיר **Kwik lock** לחומר שעבודה.
- אין להשתמש באום היידק מהיר **Kwik lock** אם הוא פגום.



במקומות אום היידק ניתן להשתמש באום היידק מהיר **Kwik Lock**. כך ניתן להחליף כליל ההשזה/חיתוך ללא שימוש בכליל העבודה.

1. הסר את הסוללה. ← עמוד 26
2. ואט בטבעת ה-O נמצאת באונג הנגדי ושיהיא תקינה לגמור.

תוצאה

- טבעת O אינה תקינה.
- אין טבעת O באונג הנגדי.
- חבר אונג נגיד חדש עם טבעת O.
- 3. נקה את האונג הנגדי ואת אום היידק מהיר.



2223267

עברית

27

4. חבר את האוגן הקדמי לציר המכשיר.
5. חבר את האביזר.
6. הביר את אום ההידוק ומהיר **Kwik lock** עד שהוא נצמודת לכלי המחובר. ⇔ במצב מוגבר הכתיבון **Kwik lock** גלוי.
7. לחץ על לחץ נעילת הציר והחזק אותו להזען.
8. המשך לשובב את הכליל בידיך בחזקה עם כיוון השעון עד שאותו ההידוק ומהיר **Kwik lock** מוחזקת היטב, ואך שחרר את לחץ נעילת הציר.

6.7.4 הסורה של כליל אום ההידוק מהיר **Kwik lock**

הסור את הסוללה. ← עמוד 26

זהירות

- סכנת **שיבירה** והרס. לחיצה על לחץ נעילת הציר בדופן שהציג מסתובב עלולה לגרום לשחרור הכליל המחובר.
↳ לחץ על לחץ נעילת הציר רק כאשר הציר אכן מסתובב.
2. לחץ על לחץ נעילת הציר והחזק אותו להזען.
 3. שחרר את אום ההידוק ומהיר **Kwik lock** באופן הבא: סובב בידיך את אום ההידוק ומהיר נגדי כיוון השעון.
 4. אם אין אפשרות לשחרר את אום ההידוק ומהיר **Kwik lock** בידיך, השתמש במפתח הברגים ושובב נגד כיוון השעון.

לעולם אין להשתמש במפתח צינורות, כדי שלא לגרום לך לאום ההידוק ומהיר **Kwik lock**.



5. שחרר את לחץ נעילת הציר והוציא את הכליל.

6.7.5 התקנת מקדח כוס

הסור את הסוללה. ← עמוד 26

1. כבר את ידיית האחידה הצדית. ← עמוד 26
2. התקן את מגן הדיסק הסטנדרטי.
3. חבר את מקדח הכלום והברג אותו ידנית.
4. לחץ על לחץ נעילת הציר והחזק אותו להזען.
5. הדק את מקדח הכלום באירועות מפתח בריגים מתאים.
6. לאחר מכן שחרר את לחץ נעילת הציר והסור את מפתח הבריגים.

6.7.6 התקנת מברשת פלדה

הסור את הסוללה. ← עמוד 26

1. כבר את ידיית האחידה הצדית. ← עמוד 26
2. התקן את מגן הדיסק הסטנדרטי.
3. חבר את מברשת הפלדה והברג אותה ידנית.
4. לחץ על לחץ נעילת הציר והחזק אותו להזען.
5. הדק את מברשת הפלדה באירועות מפתח בריגים מתאים.
6. לאחר מכן שחרר את לחץ נעילת הציר והסור את מפתח הבריגים.

6.7.7 התקנת דיסק פיבר

הסור את הסוללה. ← עמוד 26

1. כבר את ידיית האחידה הצדית. ← עמוד 26
2. התקן את מגן הדיסק הסטנדרטי.
3. חבר את הצלחת ואת דיסק הפיבר והברג והדק את אום ההידוק.
4. לחץ על לחץ נעילת הציר והחזק אותו להזען.
5. הדק את אום ההידוק בעדרת המפתח.
6. לאחר מכן שחרר את לחץ נעילת הפלה והסור את המפתח.

7 תפעול

7.1 הפעלה

1. לחץ על החלק האחורי של מותג הפעלה/כיבוי.

2. דף את מותג הפעלה/כיבוי קדימה.

↳ המנוע פועל.

3. נעל את מותג הפעלה/כיבוי.



זהירות

סכנת פגיעה. הכליל עלול להיתקע בפתאומיות.

▫ אחד במכשור תFINE בעדרת יצית האחידה הצדית והחזק אותו היטב בשתי ידיים.

7.3 חישוב

בעת החיתוך הפעיל כוח דחיפה מותן ועובד בצורה ישירה עם כל הרכיבים (זרזת עבודה כ- 90° לפני השטח של החומר שאותה חוויה).

▫ הזרק הטובה ביותר לחיתוך פרופילים וצינורות מרובעים קענים היא לעובד במקום בעל הקוטר הקטן ביותר.

**7.4 השחזה****זהירות**

סכנת פגיעה. דיסק החיתוך עלול להתפוצץ, כך שהחלקים ממנו יתעופפו ויגרמו לפציעות.

▫ לעומת זאת ניתן להשתמש בדיסק חיתוך לצורך עבודות השחזה.

▫ כדי את המכשור מצד לצד דזוזית גישה של $5 \text{ עד } 30^{\circ}$ תוך הפעלה חזק מותן.
▫ החלק שבעבודה לא יתחכם מדי, לא ישנה את צבעו ולא ייווצרו חריצים.

7.5 כיבוי

▫ לחץ על החלק האחורי של מוג הפעלה/כיבוי.
▫ מוג הפעלה/כיבוי קופץ למיקום כיבוי והמנוע כבה.

8 טיפול ותחזקה**اذנה**

סכנת פגיעה כאשר הסוללה מחוברת !

▫ לפחות ביצוע עבודות טיפול ותחזקה כלשהן יש להפסיק להסיר את הסוללה!

טיפול במיכשי

- הסר בהדרות לכלק' שבדקה.
- הסר את מסנן האבק ונבה את יצרי האוורור בהדרות מברשת יבשה.
- נקה את גוף המכשור רק בעדרת מטלית להה מעט. אין להשתמש בחומרי טיפול המיכליים סיליקון, מאחר שהם עלולים לגרום חולקי הפלסטיין.

טיפול בסוללות ליתיום-יון

- שמרו על הסוללה נקייה מלכלוק', שמן וגריד.
- נקה את גוף הממשיר ורק בעדרת מטלית להה מעט. אין להשתמש בחומרי טיפול המיכליים סיליקון, מאחר שהם עלולים לגרום חולקי הפלסטיין.
- מנע חדירת חותם.

תחזקה

- יש לבדוק באופן סדרי את כל החלקים הגלויים כדי לאטר דקים ולודוא שכל הרוכבים פועלים באופן תקין.
- אם ישנים דקים ו/או תקלות אין להפעיל את הממוצר. הבא מיד את המכשור למתקון במעבדת שירות של Hilti.
- לאחר עבודות טיפול ותחזקה יש להקפיד ולחזור את כל התקני ההגנה ולבודק את תפקוד המכשור.

▫ לצורך הפעלה בטוחה של המכשור יש להשתמש רק בחALKI חילוף וחומרים מתכליים מקוריים. את חALKI החילוף, החומרים המתכליים והאבירדים שאושרו על-ידיינו עבור המוצר של תמצא**א- Hilti Store** שלו או בכתובת: www.hilti.group.



2223267

הובלה

זהירות 

התחלת פעולה בשוגג במהלך הובלה!

↳ יש להוביל את המכשיר כהסוללה מונתקת ממנה!

↳ הוציא את הסוללה.

↳ בשום אופן אין להוביל סוללות כשהן נמצאות בין עצמים לא אරודים.

↳ לפני השימוש במכשיר בתום הובלה אורך יש לבדוק אותו ואת הסוללה לאייתור נזקים.

אחסון

זהירות 

נק לא מכוון כהסוללות פגומות או דלופות!

↳ יש לאחסן את המכשיר כהסוללה מונתקת ממנה!

↳ יש לאחסן את המכשיר וסוללה בקוקם קרייזר ויבש.

↳ עלולים אין לאחסן סוללות בשימוש, על גוף חימום או מתחור שמשה.

↳ יש לאחסן את המכשיר והסוללה הרחק מחייג ים של ילדים או אכים אל מושרים.

↳ לפני השימוש במכשיר בתום אחסון ממושך יש לבדוק אותו ואת הסוללה לאייתור נזקים.

10 תיקון תקלות

אם מתרחשת תקלה שאינה מוסברת בטבלה זו או שאיין יכול לתקן בעצמו, פנה לשירות לקוחות Hilti.

10.1 איתור תקלות

תקלה	סיבה אפשרית	פתרונות
הסוללה מתפרקת מהר מהרגיל.	טפרוטורת סביבה נמוכה מאוד. לטפרטורות החדר.	↳ אפשר לסללה להתחמם בהדרגה
הסוללה אינה בתפקת בגלל "קליק" ברו.	זדי הנעילה בסוללה מוליכים. נקה את זדי העלילה וחבר את הסוללה מחדש.	↳ נקי הפעילה בסוללה מלוליכים.
נורית אחת מהבהבתה. המכשיר אינו פועל.	הסוללה התורקנה. החולף סוללה, וטعن את הסוללה הרקה.	↳ נורית אחת מהבהבתה. החולף סוללה, וטען את הסוללה הרקה.
כל 4 הנוריות מהבהבות. המכשיר אינו פועל.	הסוללה חממה מדי או קרוה מדי. בהרואה לטפרטורות החדר.	↳ אפשר לסללה להתחמם או להתקרר בהרואה לטפרטורה חדר.
התחלקות רובה של משחזרת הזווית או הסוללה.	עומס יתר של המכשיר. שחרר את מתח ההפעלה ולהזין עליון מחדש.icut אנטה למכשיר לפועל.	↳ שחרר את מתח ההפעלה ולהזין עליון מחדש.icut אנטה למכשיר לפועל.
אין בילמת מבע.	תקלה חשמלית ההסתלה, הש枷ה עלייה, אפשר לה להתקרר וצורך קשר עם השירות של Hilti.	↳ השטמש בסוללה בעלת קיבולת מספקת.
המכשיר אינו פועל בעוצמה מלאה.	חוורה סוללה בעלת קיבולת נמוכה מדי. מספקה.	↳ השטמש בסוללה בעלת קיבולת מספקה.
אין בילמת מבע.	הסוללה התורקנה. החולף סוללה, וטען את הסוללה הרקה.	↳ נקי הפעילה בסוללה הרקה.
	עומס יתר דמci על המכשיר.	↳ כבוי את המכשיר והדליך אותו מחדש.

11 RoHS (תקנה להגבלת השימוש בחומרים מסוכנים)

בקישור הבא נמצא את טבלת החומרים המסוכנים: qr.hilti.com/r9884540
בקישור לטבלת RoHS נמצא בסוף תייעוד זה, בצד שמאל QR.

12 סולן

המוצרים של Hilti מיוצרים בחקלאי הגדול מחומרים ניידים למיחוזר. כדי שニידן יהיה למחזרם דרושה הפרדת חומרים מקצועית. במיניות רבות Hilti מקבל את המכשיר היישן שכך בחזרה לצורן מיוחד. פנה לשירות לקוחות של Hilti או למושוק.



סילוק סוללות

סילוק לא תקין של סוללות מסכן את הבריאות עקב דליפת גזים או נחלים.

אין לשלהוט סוללות פגומות ▶

כסה את החיבורים באמצעות חומר לא מוליך, כדי למנוע קצף.

סלק סוללות כך שהן לא יוכלו להגע לידייהם של ילדים.

סלק את הסוללה ב-**Hilti Store** או פנה לחברת המיזור האחראית.

◀ אין להשליך כל עבודה חשמליים, כלים אלקטרוניים וסוללות לפסולת הביתית!

**13 אחריות יצרן**

◀ אם יש לך שאלות בנוגע תפקיד האחריות, פנה למושוק **Hilti** הקרוב אליו.



2223267





Hilti Aktiengesellschaft
Feldkircherstraße 100
9494 Schaan | Liechtenstein

AG 4S-A22-125 (01)

[2018]

2006/42/EC

2014/30/EU

2011/65/EU

EN 60745-1

EN 60745-2-3

Schaan, 12/2018

A handwritten signature in black ink that reads "Paolo Luccini".

Paolo Luccini

Head of BA Quality and
Process-Management

BA Electric Tools & Accessories

A handwritten signature in black ink that reads "Tassilo Deinzer".

Tassilo Deinzer

Executive Vice President

Business Unit Power Tool &
Accessories





Hilti Corporation

L1-9494 Schaan

Tel.: +423 234 21 11

Fax: +423 234 29 65

www.hilti.group



2223267

Hilti = registered trademark of Hilti Corp., Schaan

Pos. 1 | 20190730