















en Original operating instructions

Information about the operating instructions

About these operating instructions

- Warning! Read and understand all accompanying documentation, including but not limited to instructions, safety warnings, illustrations, and specifications provided with this product. Familiarize yourself with all the instructions, safety warnings, illustrations, specifications, components, and functions of the product before use. Failure to do so may result in electric shock, fire, and/or serious injury. Save all warnings and instructions for future reference.
- Territe products are designed for professional users and only trained, authorized personnel are permitted to operate, service and maintain the products. This personnel must be specifically informed about the possible hazards. The product and its ancillary equipment can present hazards if used incorrectly by untrained personnel or if used not in accordance with the intended use.
- The accompanying documentation corresponds to the current state of the art at the time of printing. Please always check for the latest version on the product's page on Hilti's website. To do this, follow the link or scan the QR code in this documentation, marked with the symbol (2).
- Ensure that these operating instructions are with the product when it is given to other persons.

Explanation of symbols

Warnings

Warnings alert persons to hazards that occur when handling or using the product. The following signal words are used:

DANGER

DANGER !

Draws attention to imminent danger that will lead to serious personal injury or fatality.

▲ WARNING

WARNING !

Draws attention to a potential threat of danger that can lead to serious injury or fatality.

CAUTION !

 Draws attention to a potentially dangerous situation that could lead to personal injury or damage to the equipment or other property.

Symbols in the operating instructions

The following symbols are used in these operating instructions:

${}^{\odot}$	Comply with the operating instructions			
i	Instructions for use and other useful information			
	Dealing with recyclable materials			
X	Do not dispose of electric equipment and batteries as household waste			
	Hilti Li-ion battery			
Ċ∎∳n	Hilti charger			
Symbols in illustrations The following symbols are used in illustrations:				

2 These numbers refer to the illustrations at the beginning of these operating instructions.





3	The numbering reflects the sequence of operations shown in the illustrations and may devi- ate from the steps described in the text.			
(1)	Item reference numbers are used in the overview illustration and refer to the numbers used in the key in the product overview section.			
•	These characters are intended to specifically draw your attention to certain points when handling the product.			
Produ	uct-dependent symbols			
Symb	ols on the product			
The fo	Ilowing symbols can be used on the product:			
Ď	The product supports near-field communication (NFC) technology compatible with iOS and Android platforms.			
Li-Ion	Li-ion battery			
8	Never use the battery as a striking tool.			
*	Do not drop the battery. Never use a battery that has suffered an impact or is damaged in any other way.			
	Direct current (DC)			
\odot	Wear eye protection			
Ø	Always work with both hands.			

Safety

General power tool safety warnings

WARNING Read all safety warnings, instructions, illustrations and specifications provided with this power tool. Failure to follow all instructions listed below may result in electric shock, fire and/or serious injury.

Save all warnings and instructions for future reference.

The term "power tool" in the warnings refers to your mains-operated (corded) power tool or batteryoperated (cordless) power tool.

Work area safety

- Keep work area clean and well lit. Cluttered or dark areas invite accidents.
- Do not operate power tools in explosive atmospheres, such as in the presence of flammable liquids, gases or dust. Power tools create sparks which may ignite the dust or fumes.
- Keep children and bystanders away while operating a power tool. Distractions can cause you to lose control.

Electrical safety

- Power tool plugs must match the outlet. Never modify the plug in any way. Do not use any adapter plugs with earthed (grounded) power tools. Unmodified plugs and matching outlets will reduce risk of electric shock.
- Avoid body contact with earthed or grounded surfaces, such as pipes, radiators, ranges and refrigerators. There is an increased risk of electric shock if your body is earthed or grounded.
- Do not expose power tools to rain or wet conditions. Water entering a power tool will increase the risk of electric shock.
- Do not abuse the cord. Never use the cord for carrying, pulling or unplugging the power tool. Keep cord away from heat, oil, sharp edges or moving parts. Damaged or entangled cords increase the risk of electric shock.





- When operating a power tool outdoors, use an extension cord suitable for outdoor use. Use of a cord suitable for outdoor use reduces the risk of electric shock.
- If operating a power tool in a damp location is unavoidable, use a residual current device (RCD) protected supply. Use of an RCD reduces the risk of electric shock.

Personal safety

- Stay alert, watch what you are doing and use common sense when operating a power tool. Do not use a power tool while you are tired or under the influence of drugs, alcohol or medication. A moment of inattention while operating power tools may result in serious personal injury.
- Use personal protective equipment. Always wear eye protection. Protective equipment such as a dust mask, non-skid safety shoes, hard hat or hearing protection used for appropriate conditions will reduce personal injuries.
- Prevent unintentional starting. Ensure the switch is in the off-position before connecting to power source and/or battery pack, picking up or carrying the tool. Carrying power tools with your finger on the switch or energising power tools that have the switch on invites accidents.
- Remove any adjusting key or wrench before turning the power tool on. A wrench or a key left attached to a rotating part of the power tool may result in personal injury.
- Do not overreach. Keep proper footing and balance at all times. This enables better control of the power tool in unexpected situations.
- Dress properly. Do not wear loose clothing or jewellery. Keep your hair and clothing away from moving parts. Loose clothes, jewellery or long hair can be caught in moving parts.
- If devices are provided for the connection of dust extraction and collection facilities, ensure these are connected and properly used. Use of dust collection can reduce dust-related hazards.
- Do not let familiarity gained from frequent use of tools allow you to become complacent and ignore tool safety principles. A careless action can cause severe injury within a fraction of a second.

Power tool use and care

- Do not force the power tool. Use the correct power tool for your application. The correct power tool will do the job better and safer at the rate for which it was designed.
- Do not use the power tool if the switch does not turn it on and off. Any power tool that cannot be controlled with the switch is dangerous and must be repaired.
- Disconnect the plug from the power source and/or remove the battery pack, if detachable, from the power tool before making any adjustments, changing accessories, or storing power tools. Such preventive safety measures reduce the risk of starting the power tool accidentally.
- Store idle power tools out of the reach of children and do not allow persons unfamiliar with the power tool or these instructions to operate the power tool. Power tools are dangerous in the hands of untrained users.
- Maintain power tools and accessories. Check for misalignment or binding of moving parts, breakage of parts and any other condition that may affect the power tool's operation. If damaged, have the power tool repaired before use. Many accidents are caused by poorly maintained power tools.
- Keep cutting tools sharp and clean. Properly maintained cutting tools with sharp cutting edges are less likely to bind and are easier to control.
- Use the power tool, accessories and tool bits etc. in accordance with these instructions, taking into account the working conditions and the work to be performed. Use of the power tool for operations different from those intended could result in a hazardous situation.
- Keep handles and grasping surfaces dry, clean and free from oil and grease. Slippery handles and grasping surfaces do not allow for safe handling and control of the tool in unexpected situations.





Battery tool use and care

- Recharge only with the charger specified by the manufacturer. A charger that is suitable for one type of battery pack may create a risk of fire when used with another battery pack.
- Use power tools only with specifically designated battery packs. Use of any other battery packs may create a risk of injury and fire.
- When battery pack is not in use, keep it away from other metal objects, like paper clips, coins, keys, nails, screws or other small metal objects, that can make a connection from one terminal to another. Shorting the battery terminals together may cause burns or a fire.
- Under abusive conditions, liquid may be ejected from the battery; avoid contact. If contact accidentally occurs, flush with water. If liquid contacts eyes, additionally seek medical help. Liquid ejected from the battery may cause irritation or burns.
- Do not use a battery pack or tool that is damaged or modified. Damaged or modified batteries may exhibit unpredictable behaviour resulting in fire, explosion or risk of injury.
- Do not expose a battery pack or tool to fire or excessive temperature. Exposure to fire or temperature above 130° C (265 °F) may cause explosion.
- Follow all charging instructions and do not charge the battery pack or tool outside the temperature range specified in the instructions. Charging improperly or at temperatures outside the specified range may damage the battery and increase the risk of fire.

Service

- Have your power tool serviced by a qualified repair person using only identical replacement parts. This will ensure that the safety of the power tool is maintained.
- Never service damaged battery packs. Service of battery packs should only be performed by the manufacturer or authorized service providers.

Additional safety instructions

Personal safety

- ▶ Use the product and accessories only when they are in perfect working order.
- ▶ Never tamper with or modify the product or accessories in any way.
- Dust produced by grinding, sanding, cutting and drilling can contain dangerous chemicals. Some examples are: lead or lead-based paints; brick, concrete and other masonry products, natural stone and other products containing silicates; certain types of wood, such as oak, beech and chemically treated wood; asbestos or materials that contain asbestos. Determine the exposure of the operator and bystanders by means of the hazard classification of the materials to be worked. Implement the necessary measures to restrict exposure to a safe level, for example by the use of a dust collection system or by the wearing of suitable respiratory protection. The general measures for reducing exposure include:
 - working in an area that is well ventilated,
 - avoidance of prolonged contact with dust,
 - directing dust away from the face and body,
 - ▶ wearing protective clothing and washing exposed areas of the skin with water and soap.
- Touch the power tool by the insulated gripping surfaces only, when carrying out work in which the accessory tool can come into contact with concealed wiring.
- Wear protective gloves. The cut edges and metal swarf are sharp-edged and there is a risk of cut injuries. The product and the workpiece become hot in the working process and there is a risk of burn injuries.
- Wear protective gloves also when changing the accessory tool. Touching the accessory tool presents a risk of injury (cuts or burns).
- Take frequent breaks and do physical exercises to improve the blood circulation in your fingers. High vibration during long periods of work can lead to disorders of the blood vessels and nervous system in the fingers, hands and wrists.



1-11-1-1-1-1

- Wear eve protection, a hard hat and ear protection while the product is in use.
- Switch the product on only after you have brought it to the working position.
- Wait until the product has come to a complete stop before you lay it down.
- Do not work overhead with the product.
- Bisk of injury by falling tools and/or accessories. Before starting work, check that the battery and installed accessories are secure.
- Do not secure a belt hook to this power tool
- Keep the air vents clear at all times. Risk of burn injuries due to blocked air vents!

Electrical safety

- Have dirtied or dusty products that are used frequently for working on conductive materials checked at regular intervals by Hilti Service. Dust, especially dust from conductive materials, or dampness on the surface of the product can, under unfavorable conditions, lead to electric shock.
- Clean the ventilation slots on the power tool at regular intervals. The motor's fan will draw dust inside the housing and an excessive accumulation of metal dust may cause electrical hazards.
- ► Before beginning work, check the working area (e.g., using a metal detector) to ensure that no concealed electric cables or gas and water pipes are present. External metal parts of the product can become live, for example if you inadvertently damage electric wiring.
- Do not attempt to cut workpieces that could be electrically live.

Work area safety

▶ Keep the work area clean and tidy. Metal swarf is sharp and can scratch the floor surface.

Careful handling and use of electric tools

Make sure that there is no swarf or dirt on the product. When working, make sure that no swarf makes its way into the area of the on/off switch. The swarf could block the on/off switch, rendering it impossible to switch the product off.

Careful handling and use of batteries

- Comply with the following safety instructions for the safe handling and use of Li-ion batteries. Failure to comply can lead to skin irritation, severe corrosive injury, chemical burns, fire and/or explosion.
- Use only batteries that are in perfect working order.
- Treat batteries with care in order to avoid damage and prevent leakage of fluids that are extremely harmful to health!
- Do not under any circumstances modify or tamper with batteries!
- Do not disassemble, crush or incinerate batteries and do not subject them to temperatures over 80 °C (176 °F).
- Never use or charge a battery that has suffered an impact or been damaged in any other way. Check your batteries regularly for signs of damage.
- Never use recycled or repaired batteries.
- Never use the battery or a battery-operated power tool as a striking tool.
- Never expose batteries to the direct rays of the sun, elevated temperature, sparking, or open flame. This can lead to explosions.
- ► Do not touch the battery poles with your fingers, tools, iewelry, or other electrically conductive objects. This can damage the battery and also cause material damage and personal injury.
- Keep batteries away from rain, moisture and liquids, Penetrating moisture can cause short circuits. electric shock, burns, fire and explosions.
- ► Use only chargers and power tools approved for the specific battery type. Read and follow the relevant operating instructions.
- Do not use or store the battery in explosive environments.





If the battery is too hot to touch, it may be defective. Put the battery in a place where it is clearly visible and where there is no risk of fire, at an adequate distance from flammable materials. Allow the battery to cool down. If it is still too hot to touch after an hour, the battery is faulty. Consult Hilti Service or read the document entitled "Instructions on safety and use for Hilti Li-ion batteries".

B Observe the special guidelines applicable to the transport, storage and use of lithium-ion batteries. 13

Read the instructions on safety and use of **Hilti** Li-ion batteries that you can access by scanning the QR code at the end of these operating instructions.

Description				
Prod	uct overview 1			
1	Swarf cutter	7	Battery	
2	Lockable on/off switch	8	Dust filter	
3	Grip	9	Bearing pin	
4	Adjusting knob for speed	10	Blade	
5	Battery status indicator	(1)	Cut-off plate	
6	Battery release button	(12)	Mark for swarf cut-off	

Intended use

The product described is a hand-held, cordless slitting shear. It is designed for cutting sheet-like workpieces out of steel, aluminum, plastic or comparable materials. It can be used to cut along a marked line, for cutting straight or curved outside edges and for cut-outs. The strip of swarf can be cut off at any point on the workpiece.

- For this product, use only Hilti Nuron lithium-ion batteries of the B 22 series. For optimum
 performance, Hilti recommends the batteries stated in the table at the end of these operating
 instructions for this product.
- For these batteries, use only Hilti chargers of the type series stated in the table at the end of these
 operating instructions.

Items supplied

Slitting shear, Torx wrench, operating instructions

- To help ensure safe and reliable operation, use only genuine Hilti spare parts and consumables. Spare parts, consumables and accessories approved by Hilti for use with the product can be found at your local Hilti Store or online at: www.hilti.group
- Before being dispatched, the product was tested to ensure that it is in full working order. There workpiece used in testing might have left tiny scratches in the surface of the housing.

Temperature-dependent motor protection

The temperature-dependent motor protection system monitors current input and motor temperature and thus prevents the power tool overheating.

If the motor is overloaded through application of excessive working pressure, the product's performance drops noticeably or it might stall completely.

If the product stalls or slows significantly due to overloading, relieve the pressure applied to the product and then allow it to run under no load for approx. 30 seconds.

Status indicators of the Li-ion battery

Hilti Nuron Li-ion batteries can indicate state of charge, fault messages and the battery's state of health.





Indicators for state of charge and fault messages

▲ WARNING

Risk of injury by a falling battery!

If the release button is pressed with a battery inserted in the product, subsequently check that the battery is correctly re-engaged and secure.

Short-press the release button of the battery to get whichever of the following status indications is applicable at the time.

State of charge and, if applicable, faults are indicated constantly as long as the connected product is switched on.

Status	Meaning
Four (4) LEDs show constantly green	State of charge: 100 % to 71 %
Three (3) LEDs show constantly green	State of charge: 70 % to 51 %
Two (2) LEDs show constantly green	State of charge: 50 % to 26 %
One (1) LED shows constantly green	State of charge: 25 % to 10 %
One (1) LED slow-flashes green	State of charge: < 10 %
One (1) LED quick-flashes green	The Li-ion battery is completely discharged. Recharge the battery. If the LED again starts quick-flashing after the battery has been charged, consult Hilti Service.
One (1) LED quick-flashes yellow	The Li-ion battery or the product in which it is inserted is overloaded, too hot or too cold, or experiencing some other fault. Bring the product and the battery to the rec- ommended working temperature and do not overload the product when it is in use. If the message persists, consult Hilti Service.
One (1) LED shows yellow	The Li-ion battery and the product in which it is inserted are not compatible. Consult Hilti Service.
One (1) LED quick-flashes red	The Li-ion battery is locked and cannot be used. Consult Hilti Service.

Indicators showing the battery's state of health

To check the battery's state of health, press the release button and hold it down for longer than three seconds. The system does not detect a potential malfunction of the battery due to misuse, for example battery dropped or pierced, external heat damage, etc.

Status	Meaning
All LEDs show in sequence, followed by one (1) LED showing constantly green.	The battery can remain in use.
All LEDs show in sequence, followed by one (1) LED quick-flashing yellow.	The check to ascertain the battery's state of health did not complete. Repeat the procedure, or consult Hilti Service.
All LEDs show in sequence, followed by one (1) LED showing constantly red.	If a connected product can still be used, the remaining battery capacity is below 50 %. If a connected product can no longer be used, the battery has reached the end of its useful life and has to be replaced. Consult Hitti Service.





	Tec	hnica	I data
--	-----	-------	--------

	SSH 6-22
Product generation	02
Rated voltage	21.6 V
Stroke rate at idle speed	1,185 /min 2,680 /min
Weight in accordance with EPTA Procedure 01, with- out battery	2.2 kg
Ambient temperature for operation	−17 °C 60 °C
Storage temperature	−20 °C 70 °C
Batterv	

Battery operating voltage	21.6 V
Weight, battery	See the end of these operating in- structions
Ambient temperature for operation	−17 °C 60 °C
Storage temperature	−20 °C 40 °C
Battery charging starting temperature	−10 °C 45 °C

Noise information and vibration values

The sound pressure and vibration values given in these instructions were measured in accordance with a standardized test and can be used to compare one power tool with another. They can also be used for a preliminary assessment of exposure.

The data given represent the main applications of the power tool. However, if the power tool is used for different applications, with different accessory tools, or is poorly maintained, the data can vary. This can significantly increase exposure over the total working period.

An accurate estimation of exposure should also take into account the times when the power tool is switched off, or when it is running but not actually being used for a job. This can significantly reduce exposure over the total working period.

Identify additional safety measures to protect the operator from the effects of noise and/or vibration, for example: maintaining the power tool and accessory tools, keeping the hands warm, organization of work patterns.

Detailed information on the versions of the **EN 62841** standards applied here is to be found in the reproduction of the declaration of conformity £2 32.

Noise information

Typical A-weighted sound power level (L _{WA})	85 dB(A)
Typical A-weighted emission sound pressure level (L_{nA})	77 dB(A)
Uncertainty (noise values) (K _{pA} and K _{WA})	3 dB(A)

Vibration information

Triaxial vibration value (a _h)	B 22-55	8.8 m/s ²
	B 22-255	9.2 m/s ²
Uncertainty (K)	B 22-55	1.5 m/s ²
	B 22-255	1.5 m/s ²





Blade

P

Blades of different types are needed, depending on the thickness or strength of the material to be cut. Select the correct blade for the purpose from the table below.

The blades have two cutting edges. The cutting edges cannot be resharpened.

Initial equipment, as supplied ex works: SSH-CS 1.5 - 2.5 mm or SSH-CD4 mm × 0.9 mm

	SSH-CS, 0.5 - 1.5 mm, , for straight cuts	SSH-CS, 1.5 - 2.5 mm, , for straight cuts	SSH-CX, 0.5 - 1.5 mm, , for straight cuts in stainless steel	SSH-CC, 0.5 - 1.5 mm, , for curves	SSH-CD, 4 x 0.9 mm, , for spiral ducting
Permissible steel thick- ness, steel up to 400 N/mm ²	1.5 mm	2.5 mm	•/•	1.5 mm	•/•
Permissible steel thick- ness, steel up to 600 N/mm ²	1.0 mm	•/•	1.5 mm	0.8 mm	•/•
Permissi- ble materi- al thickness, aluminum up to 250 N/mm ²	2.0 mm	3.0 mm	•/•	2.0 mm	•/•
Permissi- ble material thickness, steel spiral ducting up to 400 N/mm ²	•/•	•/•	•/•	•/•	4 x 0.9 mm
Permissi- ble material thickness, steel spiral ducting up to 600 N/mm ²	•/•	•/•	•/•	•/•	4 x 0.6 mm
Starting hole diameter	17 mm	22 mm	20 mm	15 mm	18 mm
Smallest radius for curved cut-outs	80 mm	150 mm	120 mm	L 45 mm, R 80 mm	150 mm





Preparations at the workplace

▲ WARNING

Risk of injury by inadvertent starting!

- Before inserting the battery, make sure that the product is switched off.
- Remove the battery before making any adjustments to the power tool or before changing accessories.

Observe the safety instructions and warnings in this documentation and on the product.

Charging the battery

1.Before charging the battery, read the operating instructions for the charger.

- 2.Make sure that the contacts on the battery and the contacts on the charger are clean and dry.
- 3.Use an approved charger to charge the battery. 10 6

Inserting the battery

WARNING

Risk of injury by short circuit or falling battery!

- Before inserting the battery, make sure that the contacts on the battery and the contacts on the product are free of foreign matter.
- Make sure that the battery always engages correctly.
- 1. Charge the battery fully before using it for the first time.
- 2. Push the battery into the product until it engages with an audible click.
- 3.Check that the battery is seated securely.

Removing the battery

- 1.Press the battery release button.
- 2.Remove the battery from the product.

Fall arrest

▲ WARNING

Risk of injury by falling tool and/or accessory!

- ► Use only the Hilti tool tether recommended for your product.
- Prior to each use, always check the attachment point of the tool tether for possible damage.

Comply with the national regulations for working at heights.

As drop arrester for this product, use only a combination of the **Hilti** retaining strap #2293133 and the **Hilti** tool tether #2261970.

- Secure the retaining strap to the installation openings for accessories. Check that it holds securely.
- Secure one carabiner of the tool tether to the retaining strap and secure the second carabiner to a load-bearing structure. Check that both carabiners hold securely.

Comply with the operating instructions of the **Hilti** retaining strap and those of the **Hilti** tool tether.

Setting the cutting speed

▶ Set the cutting speed by turning the adjusting knob for motor speed.

Changing the blade 2

Risk of injury! The accessory tool may be hot and/or have sharp edges.

- Wear protective gloves when changing the accessory tool.
- ▶ Never lay down a hot accessory tool on a flammable surface.





Risk of damage to workpiece and blade!

Always select the correct blade for the planned use and thickness of material to be cut.



Change the blade when it becomes blunt and cutting performance diminishes.

Always replace the blade whenever you install new cutting rails.

- 1.Press out the bearing pin.
- 2.Pull the blade out of the cutting head.
- 3.Lightly grease the bearing pin and the new blade.
- 4.Insert the new blade.

5.Push the bearing pin into the hole until it engages.

Changing the cutting rails 3

Risk of injury! The accessory tool may be hot and/or have sharp edges.

- ► Wear protective gloves when changing the accessory tool.
- ▶ Never lay down a hot accessory tool on a flammable surface.

Risk of damage to product and cutting tools!

- Clean the threads before installing the securing screws.
- Always use the new securing screws supplied and tighten the screws to the specified tightening torque.
- Remove the securing screws and remove the cutting rails. If necessary, insert a suitable tool through the cutting head from above and push the cutting rails out of the guide.
- 2.Clean the thread.
- 3.Check the cutting rails:
 - ▶ If the cutting rails are blunt along only one half, reinstall them turned through 180°.
 - When either one of the two cutting rails is blunt along both halves, replace the two cutting rails as a pair.

4. Insert the cutting rails and install the securing screws.

Technical data	
Tightening torque	5 Nm

Changing the cut-off plate 4

Risk of injury! The accessory tool may be hot and/or have sharp edges.

- Wear protective gloves when changing the accessory tool.
- ▶ Never lay down a hot accessory tool on a flammable surface.

Risk of damage to product and cutting tools!

- Clean the threads before installing the securing screws.
- Always use the new securing screws supplied and tighten the screws to the specified tightening torque.
- 1.Remove the securing screw and remove the cut-off plate.
- 2.Clean the thread.





Insert the new cut-off plate and install the new securing screw.

Technical data 5 Nm

Tightening torque

Operation

Observe the safety instructions and warnings in this documentation and on the product.

Switching on

1.Press the rear section of the on/off switch.

- 2 Slide the on/off switch forward
- The motor runs
- 3 Lock the on/off switch

Cuttina 5

Before starting work, check that the cutting rails and the cut-off plate are correctly and securing seated and check the tightening torgues of the corresponding securing screws.

- 1.Switch the tool on. +12
- 2. Guide the product through the material to be cut while holding the product at an angle of about 14 ° to the material.
 - Always use a sharp blade and turn or change the cutting rails in good time.
 - Apply cutting oil or other cooling lubricant to the workpiece to prolong the useful life of the cutting tools.
- 3. If the following conditions are met, also take this action:
 - Conditions: Cutting curves
 - Guide the product slowly through the material, following the applicable radius.

Do not tilt the product to the side.

To end the cut, switch the product off.

Cutting off swarf 3

Do not cut off short lengths of swarf. The minimum length of the strip of swarf cut off must be one complete curl.

Marks on the front of the housing indicate the cut-off position.

1.With the product switched on, press the swarf cutter for 0.5 of a second.

- The strip of swarf is cut off at the mark and the cut-off process stops automatically.
- 2.Remove the cutting of swarf by hand.

Switching off

- Press the rear section of the on/off switch.
 - The on/off switch jumps into the off position and the motor stops.

Care and maintenance

A WARNING

Risk of injury with battery inserted !

Always remove the battery before carrying out care and maintenance tasks!

Care of the product

- · Carefully remove stubborn dirt.
- · Carefully clean the air vents, if present, with a dry, soft brush.



- Use only a slightly damp cloth to clean the housing. Do not use cleaning agents containing silicone as these can attack the plastic parts.
- Use a dry, clean cloth to clean the contacts of the product.

Care of the Li-ion batteries

- · Never use a battery with clogged air vents. Clean the air vents carefully using a dry, soft brush.
- Avoid unnecessary exposure of the battery to dust and dirt. Never expose the battery to high levels
 of moisture (e.g. by being dipped in water or left in the rain).
 If a battery has been soaked by moisture, treat it as a damaged battery. Isolate it in a non-flammable
 container and consult Hitti Service.
- Keep the battery free of extraneous oil and grease. Do not permit dust or dirt to accumulate unnecessarily on the battery. Clean the battery with a dry, soft brush or a clean, dry cloth. Do not use cleaning agents containing silicone as these can attack the plastic parts.

Do not touch the contacts of the battery and do not remove the factory-applied grease from the contacts.

 Use only a slightly damp cloth to clean the housing. Do not use cleaning agents containing silicone as these can attack the plastic parts.

Maintenance

- Check all visible parts and controls for signs of damage at regular intervals and make sure that they all function correctly.
- Do not use the product if signs of damage are found or if parts malfunction. Immediately have the product repaired by Hilti Service.
- After cleaning and maintenance, install all guards and protective devices and check that they are in full working order.

To help ensure safe and reliable operation, use only genuine Hilti spare parts and consumables. Spare parts, consumables and accessories approved by Hilti for use with your product can be found at your Hilti Store or online at: www.hilti.group

Transport and storage of cordless tools and batteries

Transport

Accidental starting during transport !

- Always transport your products with the batteries removed!
- Remove the battery/batteries.
- Never transport batteries loose and unprotected. During transport, batteries should be protected from excessive shock and vibration and isolated from any conductive materials or other batteries that may come in contact with the terminals and cause a short circuit. Comply with the locally applicable regulations for transporting batteries.
- Do not send batteries through the mail. Consult your shipper for instructions on how to ship undamaged batteries.
- Prior to each use and before and after prolonged transport, check the product and the batteries for damage.

Storage

▲ WARNING

Accidental damage caused by defective or leaking batteries !

- Always store your products with the batteries removed!
- Store the product and the batteries in a cool and dry place. Comply with the temperature limits stated in the technical data.





- Do not store batteries on the charger. Always remove the battery from the charger when the charging operation has completed.
- ▶ Never leave batteries in direct sunlight, on sources of heat, or behind glass.
- Store the product and batteries where they cannot be accessed by children or unauthorized persons.
- Prior to each use and before and after prolonged storage, check the product and the batteries for damage.

Troubleshooting

If a problem occurs, always observe the status indicator of the battery. See the section headed Status indicators of the Li-ion battery.

If the trouble you are experiencing is not listed in this table or you are unable to rectify the problem by yourself, contact **Hilti** Service.

Trouble or fault	Possible cause	Action to be taken
The battery runs down more quickly than usual.	Very low ambient temperature.	 Allow the battery to warm up slowly to room temperature.
The battery does not en- gage with an audible click.	The retaining lug on the battery is dirty.	 Clean the retaining lug and re-insert the battery.
The product or battery gets very hot.	Electrical fault	 Switch the product off imme- diately, remove the battery, keep it under observation, allow it to cool down and contact Hilti Service.
The motor has no braking effect.	Battery is discharged.	 Change the battery and charge the empty battery.
	Product is momentarily over- loaded.	 Switch the product off and then on again.
Product does not develop full power.	A battery with inadequate ca- pacity was used.	 Use a battery with adequate capacity.
Diminishing cutting perfor-	Blade and / or cutting rails are	 Change the blade. 10
mance	blunt.	 Change the cutting rails. 11
LEDs of the battery show nothing	Battery defective.	 Contact Hilti Service.

Disposal

▲ WARNING

Risk of injury due to incorrect disposal! Health hazards due to escaping gases or liquids.

- DO NOT send batteries through the mail!
- Cover the terminals with a non-conductive material (such as electrical tape) to prevent short circuiting.
- Dispose of your battery out of the reach of children.
- Dispose of the battery at your Hilti Store, or consult your local governmental garbage disposal or public health and safety resources for disposal instructions.

Most of the materials from which **Hilti** products are manufactured can be recycled. The materials must be correctly separated before they can be recycled. In many countries, your old tools, machines or appliances can be returned to **Hilti** for recycling. Ask **Hilti** Service or your Hilti sales representative for further information.





Do not dispose of power tools, electronic equipment or batteries as household waste!

Manufacturer's warranty

► Please contact your local Hilti representative if you have questions about the warranty conditions.

Further information

For more information on operation, technology, environment and recycling, follow this link: gr.hilti.com/manual/?id=2327536&id=2332250

This link is also to be found in these operating instructions in the form of a QR code, indicated by the symbol 🚱.





he הוראות הפעלה מקוריות

מידע על הוראות ההפעלה

על הוראות הפעלה אלו

- אזהרה! לפני השימוש במוצר יש לקרוא ולהבין את הוראות ההפעלה המצורפות למוצר, כולל ההערות, הוראות הבטיחות והאזהרות, האיזרים והמפרטים. יש ללמוד במיוחד את כל הוראות הבטיחות, האזהרות, המפרטים והפונקציות השונות של המוצר. התעלמות מהנחיה זו מובילה לסכנת התחשמלות, שריפה ופציעות קשות. שמור את הוראות ההפעלה, כולל כל הוראות הבטיחות והאזהרות לצורך שימוש בעתיד.
- הוראות ההפעלה המצורפות נכתבו בהתאם לידיעות הטכנולוגיות במועד השליחה לדפוס. את הגרסה העדכנית ביותר אפשר למצוא תמיד בדף המוצר של Hitti. כדי להגיע לשם, יש לסרוק את קוד ה-QR בהוראות ההפעלה האלה, מסומן בסמל ?
 - אם אתה מעביר את המוצר לאדם אחר, מסור לו גם את הוראות ההפעלה האלה.

הסבר הסימנים

אזהרות

האזהרות מזהירות מפני סכנות בשימוש במוצר. במדריך זה מופיעות מילות המפתח הבאות:

🔺 סכנה

סכנה !

▶ מציינת סכנה מיידית, המובילה לפציעות גוף קשות או למוות.

אזהרה \Lambda

אדהרה !

▶ מציינת סכנה אפשרית, שיכולה להוביל לפציעות גוף קשות או למוות.

זהירות 🔬

זהירות !

▶ מציינת מצב שעלול להיות מסוכן ולהוביל לפציעות גוף או לנזקים לרכוש.

סמלים בהוראות ההפעלה

הסמלים הבאים מופיעים בהוראות הפעלה אלה:



שים לב להוראות ההפעלה





טיפול נכוו בחומרים למיחזור

אין להשליך לפסולת הביתית מכשירים חשמליים וסוללות 🏹

סוללת ליתיום-יוו Hilti

מטען Hilti 🖼

סמלים באיורים

הסמלים הבאים משמשים באיורים:

מספרים אלה מפנים לאיור המתאים בתחילת הוראות הפעלה אלה.	
המספרים באיורים משקפים את רצף הפעולות, והם עשויים להיות שונים מרצף הפעולות המצוינות בטקסט.	
מספרי הפריטים מופיעים באיור סקירה ותואמים את המספרים במקרא בפרק סקירת המוצר .	





סימו זה אמור לעורר את תשומת לבד המיוחדת בעת השימוש במוצר.

סמלים ספציפיים למוצר

סמלים על המוצר

הסמלים הבאים עשויים להופיע על המוצר:

đ	המוצר תומך בטכנולוגיית NFC, התואמת את פלטפורמות iOS ו-Android.
Li-Ion	סוללת ליתיום-יון
8	לעולם אין להשתמש בסוללה כפטיש.
\$	אין להפיל את הסוללה. אין להשתמש בסוללה שנחבטה או שניזוקה באופן אחר.
	זרם ישר
•	השתמש במגני עיניים
\bigotimes	עבוד תמיד בשתי ידיים.
בטיחוו	1

הוראות בטיחות כלליות לכלי עבודה חשמליים

אזהרה קרא את כל הוראות הבטיחות, ההנחיות, האיורים והנתונים הטכניים המצורפים לכלי העבודה **החשמלי.** אי ציות להנחיות עלול להוביל להתחשמלות. לשרפה ו/או לפציעות קשות.

שמור את כל הוראות הבטיחות וההנחיות לעיון בעתיד.

המונח "כלי עבודה חשמלי" המשמש בהוראות הבטיחות מתייחס לכלי עבודה חשמליים המחוברים לרשת החשמל (עם כבל חשמל) או לכלי עבודה חשמליים המופעלים באמצעות סוללה נטענת (ללא כבל חשמל).

בטיחות במקום העבודה

- שמור על אזור העבודה שלך בקי ודאג לתאורה מספקת. חוסר סדר או תאורה לקויה במקום העבודה עלולים לגרום לתאונות.
- אין להפעיל את כלי העבודה החשמלי בסביבה שקיימת בה סכנת פיצוץ או שישנם בה נוזלים, גזים או אבק אין להפעיל את כלי **דליקים.** כלי עבודה חשמליים יוצרים ניצוצות. שעלולים להצית את האבק או האדים.
- ► הרחק ילדים ואנשים אחרים מכלי העבודה החשמלי במהלד השימוש בו. אם דעתר תוסח אתה עלול לאבד את השליטה במכשיר.

רטיחות רחשמל

- עקע החשמל של כלי העבודה החשמלי חייב להתאים לשקע החשמל. אסור לשנות בשום אופו את תקע החשמל. אל תשתמש בשקע מתאם ביחד עם כלי עבודה חשמליים הכוללים הכנת הארקה. שימוש בתקעים חשמליים שלא עברו שינוי ושקעי חשמל מתאימים מפחית את הסיכוו להתחשמלות.
- ► מנע מגע של הגוף בשטחים מוארקים כגון צינורות, גופי חימום, תנורים ומקררים. קיימת סכנה גבוהה להתחשמלות כאשר הגוף שלד מוארק.
- ► הרחק כלי עבודה חשמליים מגשם או רטיבות. חדירת מים לכלי העבודה החשמלי מגדילה את הסיכוו להתחשמלות.
- ▶ אל תשתמש בכבל החשמל למטרות שלא לשמן הוא נועד, לדוגמה: אל תרים את כלי העבודה החשמלי באמצעות הכבל ואל תנסה לנתק את התקע משקע החשמל במשיכה מהכבל. הרחק את הכבל מחום. שמו. פינות חדות או מחלקים בעים. כבלים שניזוקו או שהסתבכו בחלקים אחרים מגדילים את הסיכון להתחשמלות.
- כאשר אתה עובד עם כלי העבודה החשמלי בחוץ, השתמש רק בכבל מאריך המיועד לשימוש חיצוני. שימוש בכבל מאריך המתאים לשימוש חיצוני מפחית את הסיכוי להתחשמלות.
- ► אם לא ניתן להימנע משימוש בכלי העבודה החשמלי בסביבה לחה, השתמש בממסר פחת. השימוש בממסר פחת מפחית את הסיכוו להתחשמלות.





בטיחות של אנשים

- ► היה ערני, שים לב למה שאתה עושה, ופעל בתבונה כאשר אתה עובד עם כלי עבודה חשמלי. אל תפעיל כלי עבודה חשמליים כשאתה עייף או תחת השפעת סמים, אלכוהול או תרופות. די ברגע אחד של חוסר תשומת-לב בזמן השימוש בכלי העבודה החשמלי כדי לגרום פציעות קשות.
- ◄ לבש תמיד ציוד מגן ומשקפי מגן. לבישת ציוד מגן אישי, כגון מסכת אבק, נעלי בטיחות מונעות החלקה, קסדת מגן או מגני שמיעה בהתאם לסוג השימוש בכלי העבודה החשמלי מקטינה את הסיכון לפציעות.
- ► מבע הפעלה בשוגג. ודא שכלי העבודה החשמלי כבוי לפני שאתה מחבר אותו לאספקת החשמל ו/או לפני שאתה מחבר אותו לא מבני שאתה מחבר את הסוללה ולפני הרמתו. אל תניח את אצבעך על המתג בזמן שאתה נושא את המכשיר ואל תחבר אותו לאספקת החשמל כאשר הוא מופעל, אחרת עלולות להיגרם תאונות.
- ► הרחק כלי כוונון או מפתחות ברגים לפני שאתה מפעיל את כלי העבודה החשמלי. כלי עבודה או מפתחות הנמצאים בקרבת חלקים מסתובבים עלולים לגרום פציעות.
- ► הימנע מתנוחות גוף לא נכונות. עמוד באופן יציב ושמור תמיד על שיווי משקל. כך תוכל לשלוט טוב יותר בכלי העבודה החשמלי במצבים לא צפויים.
- ► לבש בגדים מתאימים. אל תלבש בגדים רחבים או תכשיטים. הרחק את השער, הבגדים וכפפות מחלקים נעים. בגדים רופפים, תכשיטים ושיער ארוך עלולים להיתפס בחלקים נעים.
- ► כאשר ניתן להתקין התקני שאיבת אבק ולכידה יש לוודא שהם מחוברים לחשמל, ויש להקפיד להשתמש בהם בצורה נכונה. שימוש בהתקן שאיבת אבק מקטין את הסכנות הנובעות מהאבק.
- ► אל תהיה שאנן בנושאי בטיחות ואל תתעלם מהוראות בטיחות של כלי עבודה חשמליים, גם אם שהשתמשת במכשיר פעמים רבות ואתה מכיר אותו היטב. התנהגות רשלנית עלולה להוביל לפציעות קשות בתוך שניות. שימוש וטיפול בכלי העבודה החשמלי
- ► אל תפעיל עומס רב מדי על המכשיר. השתמש בכלי העבודה החשמלי המתאים לעבודה שאתה מבצע. כלי העבודה החשמלי המתאים מבטיח לך עבודה טובה ובטוחה יותר בתחום ההספק הנקוב.
- אל תשתמש בכלי העבודה אם המתג שלו אינו תקין. כלי עבודה חשמלי שלא ניתן עוד להפעיל או לכבות אותו מהווה סכנה ויש לתקנו.
- ► נתק את תקע החשמל מהשקע ו/או הסר את הסוללה לפני שאתה מבצע כוונונים במכשיר, מחליף כלים או לאחר שאתה מפסיק לעבוד עם המכשיר. אמצעי זהירות זה מונע הפעלה בשוגג של כלי העבודה החשמלי.
- ▶ שמור כלי עבודה חשמליים שאינם בשימוש הרחק מהישג ידם של ילדים. אל תאפשר לאנשים שאינם יודעים כיצד להשתמש במכשיר או שלא קראו את ההוראות להשתמש במכשיר. כלי עבודה חשמליים הם מסוכנים כאשר משתמשים בהם אנשים חסרי ניסיון.
- ► טפל בכלי עבודה חשמליים ובאביזרים בהקפדה. בדוק אם החלקים הנעים פועלים בצורה חלקה ואינם נתקעים, אם ישנם חלקים שבורים או מקולקלים המשבשים את הפעולה התקינה של כלי העבודה החשמלי. לפני השימוש במכשיר דאג לתיקון חלקים לא תקינים. תאונות רבות נגרמו עקב תחזוקה לקויה של כלי עבודה חשמליים.
- שמור על כלי החיתוך חדים ונקיים. כלי חיתוך מטופלים היטב, שלהביהם חדים נתקעים פחות וקלים יותר לתפעול.
- ► השתמש בכלי העבודה החשמלי, באביזרים, בכלי העבודה הנוספים וכן הלאה בהתאם להוראות אלה. התחשב בתנאי העבודה ובפעולה שעליך לבצע. שימוש בכלי העבודה החשמלי למטרות אחרות מאלה שלשמן הוא מיועד עלול להיות מסוכן.
- ▶ שמור על ידיות ואזורי אחיזה בקיים מלכלוך משומן ומגריז. ידיות ואזורי אחיזה חלקים אינם מאפשרים תפעול בטוח ושליטה טובה בכלי העבודה החשמלי במצבים לא צפויים.

שימוש וטיפול בכלי עבודה נטענים

- ► טען את הסוללות רק במטענים שהומלצו על ידי היצרן. טעינה של סוללה במטען המיועד לטעינה של סוללות מסוג אחר עלולה לגרום לשרפה.
- השתמש לשם כך רק בסוללות המתאימות לכלי העבודה החשמלי. שימוש בסוללות אחרות עלול לגרום לשרפות.
- ► שמור סוללות שאינן בשימוש הרחק ממהדקי נייר משרדיים, ממטבעות, מפתחות, מסמרים, ברגים או חפצים מתכתיים קטנים אחרים שיכולים לגשר בין המגעים. קצר בין מגעי הסוללה עלול לגרום לכוויות או לשרפה.
- ► שימוש שגוי עלול לגרום לדליפת נוזלים מהסוללה. אל תיגע בנוזלים אלה. אם נגעת בהם במקרה, שטוף את האימוש שימוש שימוש שימוש אלו לגרום לגירויים בעור ולכוויות.
- ► אין להשתמש בסוללה ששונתה או שניזוקה. סוללות שניזוקו או שנערכו בהן שינויים עשויות להגיב בצורה לא צפויה ולגרום לשרפה, לפיצוץ ולפציעות.





- ► אין לחשוף סוללות לאש או לטמפרטורות גבוהות. אש או טמפרטורות גבוהות מ-265°F) (265°F) עלולות לגרום לפיצוץ.
- ▶ ציית לכל ההנחיות הנוגעות לטעינה, ואף פעם אל תטען את הסוללה או את הכלי עם הסוללה בסביבה שהטמפרטורה בה נמצאת מחוץ לטווח המצוין בהוראות ההפעלה. טעינה שגויה או טעינה בטמפרטורה שנמצאת מחוץ לטווח המצוין בהוראות ההפעלה עלולה להרוס את הסוללה ולהגביר את הסיכון לשרפה.

שירות

- ► דאג לתיקון כלי העבודה החשמלי שלך רק בידי טכנאים מוסמכים, המשתמשים בחלקי חילוף מקוריים בלבד. כך תבטיח שמירה על בטיחות העבודה במכשיר.
 - אל תטפל בעצמך בסוללות שניזוקו. רק היצרן או מעבדה מורשית מטעמו רשאים לטפל בסוללות.

הוראות בטיחות נוספות

בטיחות של אנשים

- ▶ השתמש במוצר ובאביזרים רק בתנאי שהם נמצאים במצב טכני מושלם.
 - אל תבצע בשום אופן שינויים או מניפולציות במוצר או באביזרים.
- ► אבק שנוצר במהלך ליטוש, השחזה, חיתוך או קידוח עלול להכיל כימיקלים מסוכנים. להלן כמה דוגמאות: עופרת או צבעים על בסיס עופרת, לבנים, בטון וחומרי קיר אחרים, אבן טבעית ומוצרים אחרים המכילים סיליקט; עצים מסוימים, כגון אלון, בדן עוץ שעבר טיפול כימי; אסבסט או חומרים המכילים אסבסט. יש למדוד את חשיפת המשממש והאנוים, כגון אלון, בדן עוץ שעבר טיפול כימי; אסבסט או חומרים המכילים אסבסט. יש למדוד את חשיפת המשממש והאנוים כגון אלון, בדן עוץ שעבר טיפול כימי; אסבסט או חומרים המכילים אסבסט. יש למדוד את חשיפת המשממש והאנוים כגון אלון, בדן עוץ שעבר טיפול כימי; אסבסט או חומרים המכילים אסבסט. יש למדוד את חשיפת המשממש והאנשים בכאון אלון, בדן עוץ שעבר טיפול כימי; אסבסט או חומרים המכילים אסבסט. יש למדוד את חשיפת המשממש והאנשים בביה על פי דירוג הסכנה של החומרים שבהם עובדים. נקט את האמצעים הדרושים כדי לשמור את החשיפה ברמה בטוחה, לדוגמה שימוש במערכות שאיבת אבק או לבישת מסיכת נשימה מתאימה. להלן רשימה של אמצעים כליים להפחתת החשיפה:
 - עבודה באזור מאוורר היטב. 🕨
 - רימנעות ממגע ממושך עם האבק. ◄
 - סילוק האבק מהפנים והגוף.
 - ▶ לבישת ביגוד מגן ושטיפת אזורים חשופים במים וסבון.
- ► כאשר אתה מבצע עבודות שבהן הכלי עלול לפגוע בקווי חשמלי מוסתרים החזק את כלי העבודה החשמלי רק במקומות האחיזה המבודדים.
- ◄ לבש כפפות מגן. הלהבים ושבבי המתכת הנוצרים חדים: סכנת פציעה. המוצר והחלק המעובד מתחממים במהלך העיבוד: סכנת כווייה.
 - ▶ לבש כפפות בטיחות גם בעת החלפת כלי. מגע בכלי עלול לגרום לפציעות ולכוויות.
- ◄ ערוך הפסקות תכופות ותרגילים לשיפור זרימת הדם לאצבעות. בעבודה ממושכת הרעידות החזקות מהמכשיר עשויות לגרום להפרעות בכלי הדם או במערכת העצבים של האצבעות, כפות הידיים או שורשי כף היד.
 - ▶ לבש מגני עיניים, קסדת עבודה ומגני שמיעה בזמן העבודה.
 - ▶ הדלק את המכשיר רק לאחר שהבאת אותו לעמדת העבודה.
 - ר המתן עד לעצירה מלאה של המוצר לפני שאתה מניח אותו. ◄
 - אל תעבוד עם המוצר מעל הראש.
- ► סכנת פציעה מכלי עבודה ו/או אביזרים נופלים. לפני תחילת העבודה בדוק שהסוללה והאביזר המותקן מחוברים היטב.
 - ◄ אל תחבר תפס חגורה לכלי עבודה זה.
 - ◄ שמור על חריצי האוורור פנויים תמיד. סכנת כוויה כשחריצי האוורור מכוסים!

בטיחות בחשמל

- ◄ מוצרים שמתלכלכים עקב עבודה תכופה בחומרים מוליכים יש להביא באופן סדיר לבדיקה במעבדות של Hilti. לחות ואבק שנדבק לפני השטח של המוצר, ובמיוחד אבק מחומרים מוליכים, עלולים לגרום התחשמלות.
- ► נקה באופן סדיר את חריצי האוורור של כלי העבודה החשמלי שלך. מפוח המנוע יונק אבק לתוך המארז, והצטברות מופרזת של אבק מתכות יכולה ליצור סיכונים חשמליים.
- ▶ לפני תחילת העבודה בדוק את אזור העבודה כדי לאתר קווי חשמל וצינורות גז או מים מוסתרים; השתמש לכך, לדוגמה, בגלאי מתכות. חלקים מתכתיים חיצוניים של המוצר עלולים להוליך חשמל במקרה שתפגע בטעות כבל חשמל.
 - אל תחתוך חלקים שעשויים להיות מוליכים.

בטיחות במקום העבודה

▶ שמור על הניקיון באזור העבודה. שבבי מתכת הם חדים ועלולים לשרוט את הרצפה.





טיפול ושימוש קפדניים בכלי עבודה חשמליים

ודא שהמוצר נקי משבבים או לכלור. במהלד העבודה הקפד למנוע חדירת שבבים לאזור של מתג ההפעלה/כיבוי. השררים עלולים לחסום את מתג ההפעלה/כירוי ולמנוע את הירולת לררות את המוצר

טיפול ושימוש קפדניים בסוללות נטענות

- אשים לב להוראות הבטיחות הבאות בנושא טיפול בטוח ושימוש בטוח בסוללות ליתיום-יוו. אי הקפדה עשוי להוביל לגירויים בעור. פציעות צריבה קשות. כוויות כימיות. לדליקה ו/או לפיצוץ.
 - השתמש רק בסוללות שנמצאות במצב טכני מושלם.
 - טפל בסוללות בהקפדה כדי למונע נזקים ולמנוע דליפה של נוזלים מסוכנים לבריאות!
 - בשום אופו אסור להכניס שינויים כלשהם בסוללות!
 - ► איו לפרק. למעוד. לחמם לטמפרטורה גבוהה מ-80°C (176°F) או לשרוף את הסוללות הנטענות.
- אל תשמש או תטעו סוללות שקיבלו מכה או ניזוקו בדרר אחרת. בדוק את הסוללות שלר באופו סדיר כדי לזהות סימני נזק.
 - בשום אופו איו להשתמש בסוללות ממוחזרות או מתוקנות.
 - לעולם איו להושתמש בתוללה או בכלי עבודה חשמלי המופעל בתוללה בפנויוש
- ▶ לעולם איו לחשוף את הסוללה לקרינת שמש ישירה. לטמפרטורה גבוהה. לניצוצות או ללהבה גלויה. זה עלול להוביל לפיצוץ.
- אל תיגע בקוטבי הסוללה באצבעותיד. באמצעות כלי עבודה. תכשיטים או באמצעות עצמים מוליכי חשמל אחרים. זה עלול לפגוע בסוללה כמו גם לגרום נזקי רכוש ופציעות.
 - ► הרחק סוללות מרטיבות ונוזלים. חדירת לחות עלולה לגרום קצר. התחשמלות. כוויות, דליקה ופיצוץ.
- ▶ השתמש רק במטענים ובכלי עבודה חשמליים המיועדים לסוג סוללה זה. שים לב בנושא זה לדרישות המופיעות בהוראות ההפעלה המתאימות.
 - ▶ איו להשתמש בסוללה בסביבה נפיצה או לאחסו אותה בסביבה נפיצה.
- אם הסוללה חמה כל כד שלא ניתו לגעת בה. ייתכו שהיא אינה תקינה. הנח את הסוללה במקום לא דליק. גלוי. רחוק מספיק מחומרים דליקים. אפשר לסוללה להתקרר. אם כעבור שעה הסוללה עדיין חמה מדי לנגיעה, אז היא פגומה. פנה לשירות של Hilti או קרא את המסמר "הנחיות בנושא בטיחות ושימוש בסוללות ליתיום-יוו של Hilti".

שים לב לתקנות המיוחדות החלות על הובלה, אחסון ושימוש בסוללות ליתיום-יוו. 🕮 27 OR- קרא את ההנחיות בנושא בטיחות ושימוש בסוללות ליתיום-יוו של Hilti: אפשר להגיע אליהו דרד קוד ה שבסוף הוראות אלה.

חיאור

סקירת המוצר

- מפריד שבבים £
- 2 מתג הדלקה/כיבוי ננעל
 - 3 4 5 ידית
 - גלגל כוונוו סל"ד
 - תצוגת מצב סוללה
 - 6 לחצו שחרור סוללה

 $\widetilde{\mathbb{O}}$ Ĩ סימוו להפרדת שבבים (12)

(8)

Ť

סוללה $\widehat{\mathbf{T}}$

סכיו

מסנן אבק

בורג מסב

לוחית חיתור

שימוש בהתאם לייעוד

המוצר המתואר הוא מספרי פח ידניים המופעלים באמצעות סוללה. הוא מיועד להפרדה ביו חלקים מעובדים בצורת לוח. העשויים פלדה, אלומיניום, פלסטיק או חומר שקול, אפשר להשתמש בו לצורר חיתור לפי סימוו. חיתור של שפות חיצוניות ישרות או מעוקלות וחתכים פנימיים. אפשר לחתוד את השבב הנותר בחלק המעובד בהתאם לצורד.

- השתמש עבור מוצר זה רק בסוללות ליתיום-יון של Hilti Nuron מסדרת הדגמים B 22. כדי להשיג ביצועים אופטימליים. Hilti ממליצה להשתמש עבור מוצר זה בסוללות המצוינות בסוף הוראות ההפעלה האלה.
- השתמש עבור סוללות נטענות אלה רק במטענים של Hilti מסדרות הדגמים המצוינות בטבלה בסוף הוראות הפעלה אלה





מפרט אספקה

מספרי חריץ, מפתח טורקס, הוראות הפעלה



לצורד הפעלה בטוחה של המכשיר יש להשתמש רק בחלקי חילוף וחומרים מתכלים מקוריים. את חלקי החילוף. החומרים המתכלים והאביזרים שאושרו על-ידנו עבור המוצר שלר תמצא ב-Hilti Store שלר או בכתובת: www.hilti.group

התפקוד התקין של המוצר נבדק לפני האספקה. עקב כך ייתכן שבמהלך הבדיקה גוף המכשיר ספג שריטות קלות.

הגנה תלוית-טמפרטורה

הגנת המנוע תלוית-הטמפרטורה מפקחת על צריכת החשמל וכו על טמפרטורת המנוע ומגנה על המוצר מפני התחממות יתר.

כאשר ישנו עומס יתר על המנוע עקב הפעלת כוח לחיצה חזק מדי. הספק המוצר יפחת משמעותית וייתכו אפילו שהמוצר ייעצר לגמרי.

אם עקב עומס יתר המוצר נעצר או שמהירות הסיבוב שלו פוחתת, יש להפחית את העומס על המוצר ולהמשיך להפעיל אותו במצב סרק במשך כ-30 שניות.

תצוגות סלולת הליתיום-יוו

סוללות ליתיום-יוו של Hilti Nuron יכולות להציג את רמת הטעינה. הודעות שגיאה ואת מצב הסוללה. תצובות ושל רמת הנועירה והודעות ושביאה

אזהרה \Lambda

סכנת פציעה עקב סוללה שנפלה!

▶ לאחר לחיצה על לחצן שחרור הנעילה בסוללה מחוברת, יש לוודא שהסוללה ננעלת בחזרה במקום.

כדי לראות אחת מהתצוגות האלה. לחץ קצרות על לחצו שחרור הסוללה.

רמת הטעינה כמו גם תקלות אפשריות יוצגו ברציפות כל עוד המוצר המחובר מופעל.

משמעות	מצב
רמת טעינה: 100% עד 71%	ארבע (4) נוריות מאירות ברציפות בירוק
רמת טעינה: 70% עד 51%	שלוש (3) נוריות מאירות ברציפות בירוק
רמת טעינה: 50% עד 26%	שתי (2) נוריות מאירות ברציפות בירוק
רמת טעינה: 25% עד 10%	נורית אחת (1) מאירה ברציפות בירוק
רמת טעינה: < 10%	נורית אחת (1) מהבהבת לאט בירוק
סוללת הליתיום-יון ריקה לגמרי. טען את הסוללה. אם הנורית ממשיכה להבהב גם לאחר טעינה סוללות, פנה לשירות של Hilti.	נורית אחת (1) מהבהבת מהר בירוק
סוללת הליתיום-יון או המוצר המחובר אליה חמים מדי, קרים מדי, תחת עומס-יתר או ישבה תקלה אחרת. הבא את המוצר והסוללה לטמפרטורת העבודה המומלצת, ואל תפעיל עומס מופרד על המוצר במהלך השימוש. אם ההודעה עדיין קיימת, פבה לשירות של Hilti.	נורית אחת (1) מהבהבת מהר בצהוב
סוללת הליתיום-יון והמוצר המחובר אליה אינם תואמים. אנא פנה למעבדת שירות של Hilti.	נורית אחת (1) מאירה בצהוב.
סוללת הליתיום-יון חוסמה, ואי אפשר להמשיך ולהשתמש בה. אנא פנה למעבדת שירות של Hilti .	נורית אחת (1) מהבהבת במהירות באדום

תצוגות של מצב הסוללה

כדי לבדוק את מצב הסוללה, החזק את לחצן השחרור לחוץ במשך יותר משלוש שניות רצופות. המערכת אינה מזהה תקלה פוטנציאלית בתפקוד הסוללה עקב שימוש לא נכון, לדוגמה נפילה, חתכים או נזקי חום חיצוניים וכן הלאה.





משמעות	מצב
אפשר להמשיך ולהשתמש בסוללה.	כל הנוריות מאירות כאור רץ, ולאחר מכן נורית אחת (1)
	מאירה ברציפות בירוק.
אי אפשר היה להשלים את בירור מצב הסוללה. חזור על	כל הנוריות מאירות כאור רץ, ולאחר מכן נורית אחת (1)
התהליך או פנה לשירות של Hilti .	מהבהבת מהר בצהוב.
אם עדיין אפשר להמשיך להשתמש במוצר המחובר,	כל הנוריות מאירות כאור רץ, ולאחר מכן נורית אחת (1)
קיבולת הסוללה הנותרת נמוכה מ-50%.	מאירה ברציפות באדום.
אם אי אפשר עוד להמשיך להשתמש במוצר המחובר,	
אז הסוללה נמצאת בסוף חיי השירות שלה ויש להחליף	
אותה. אנא פנה למעבדת שירות של Hilti .	L

נתונים טכניים

	SSH 6-22
דור המוצר	02
מתח נקוב	21.6 וולט
מהירות הלהב במהירות סרק	1,185 סל"ד 2,680 סל"ד
משקל לפי EPTA Procedure 01 ללא סוללה	2.2 ק"ג
טמפרטורת סביבה בעבודה	60 °C −17 °C
טמפרטורת אחסון	70 °C −20 °C
מוללה במעובת	

סוללה נטענת

מתח עבודה עם סוללה נטענת	21.6 וולט
משקל הסוללה	ראה בסוף הוראות ההפעלה האלה
טמפרטורת סביבה בעבודה	60 °C −17 °C
טמפרטורת אחסון	40 °C −20 °C
טמפרטורת הסוללה בתחילת הטעינה	45 °C −10 °C

מידע על רעשים וערכי רעידות

ערכי לחץ הקול והרעידות המצוינים בהוראות אלה נמדדו בהתאם לנוהל המדידה התקני, וניתן להשתמש בהם לצורך השוואה בין כלי עבודה חשמליים. הם מתאימים גם להערכה זמנית של העומסים.

הנתונים המצוינים תקפים לשימושים העיקריים בכלי העבודה החשמלי. אולם אם משתמשים בכלי העבודה החשמלי לשימושים אחרים, בשילוב אבידרים אחרים או אם המכשיר אינו עובר תחזוקה מספקת, הנתונים עשויים להשתנות. בעקבות זאת פריסת העומסים למשך זמן העבודה כולו עשויה להיות גבוהה באופן משמעותי.

לצורך הערכה מדויקת של העומסים יש לקחת בחשבון גם את הזמנים שבהם כלי העבודה כבוי או שבהם הוא אמנם פועל אך אינו בשימוש בפועל. בעקבות זאת פריסת העומסים למשך זמן העבודה כולו עשויה להיות נמוכה באופן משמעותי. יש לקבוע הנחיות בטיחות נוספות להגנה על המשתמש מפני ההשפעות של קול ו/או רעידות, כגון: תחזוקה של כלי העבודה החשמלי ושל כלי העבודה המחוברים, שמירה על ידיים חמות, ארגון תהליכי העבודה.

.33 🖅 מידע מפורט על גרסאות תקני EN 62841 הישימים תמצא בתמונת הצהרת התאימות 🕄 33.

מידע על רעשים

מת הספק קול אופיינית בדירוג A (L _{WA})	85 dB(A)
מת לחץ קול אופיינית בדירוג A (L _{pA})	77 dB(A)
(K _{WA} -ו K _{pA}) (ערכי קול) (אי-ודאות (ערכי קול)	3 dB(A)

מידע על רעידות

8.8 מ'/שנ' ²	B 22-55	(a _h) ערך רעידות מרחבי
9.2 מ'/שנ ^{י2}	B 22-255	





55 (K) י ודאות	B 22-55	1.5 מ'/שנ' ²
55	B 22-255	1.5 מ'/שנ' ²

סכין

כתלות בעובי או בחוזק של החלק, נחוצים סוגי סכינים שונים. בחר מהטבלה הבאה את הסכין המתאים למטרת השימוש.

בסכינים קיימים שני להבים. אין אפשרות להשחיז את הלהבים. 😭

	ציאה מהמפעל: 2.5 – 1.5 SSH-CS מ"מ או 4 SSH-CD מ"מ × 0.9 מ"מ	אבזור ביא
--	---	-----------

SSH-CD,	SSH-CC,	SSH-CX,	SSH-CS,	SSH-CS,	
,מ"מ, 0.9 4 x	,n"n 0.5–1.5	,n"n 0.5–1.5	, n"n 1.5–2.5	0.5–1.5 מ"מ,	
ס, לצינורות 🔘	לעיקולים 🦰	💢, לחתכים	—, לחתכים	—, לחתכים	
ספירליים		ישרים בפלדת	ישרים	ישרים	
		אל-חלד			
•/•	1.5 מ"מ	•/•	2.5 מ"מ	1.5 מ"מ	עובי חומר מותר,
					פלדה, עד 400
					ניוטון/ממ"ר
•/•	8.0 מ"מ	1.5 מ"מ	•/•	1.0 מ"מ	עובי חומר מותר,
					פלדה, עד 600
					ניוטון/ממ"ר
•/•	2.0 מ"מ	•/•	3.0 מ"מ	2.0 מ"מ	עובי חומר מותר,
					אלומיניום, עד
					250 ניוטון/ממ"ר
4 x 0.9 מ "מ	•/•	•/•	•/•	•/•	עובי חומר מותר,
					צינורות
					ספירליים
					מפלדה, עד
					400 ביוטון/ממ"ר
4 x 0.6 מ "מ	•/•	•/•	•/•	•/•	עובי חומר מותר,
					צינורות
					ספירליים
					מפלדה, עד
					600 ניוטון/ממ"ר
18 מ"מ	15 מ"מ	20 מ"מ	22 מ"מ	17 מ"מ	קוטר קדח
					התחלתי
150 מ"מ	L - 45 מ"מ, R	120 מ"מ	150 מ"מ	80 מ"מ	הרדיוס הקטן
	- 80 מ"מ				ביותר בחיתוכים
					מעוקלים

הכנה לעבודה

אזהרה 🧄

סכנת פציעה עקב התחלת תנועה בשוגג!

▶ לפני חיבור הסוללה ודא שהמוצר כבוי.

▶ הסר את הסוללה לפני שאתה מבצע כוונונים כלשהם במכשיר או מחליף אביזרים.

ציית להוראות הבטיחות והאזהרות שבתיעוד זה ולאלה המצוינות על המוצר.

טעינת סוללה

.1קרא את הוראות ההפעלה של המטען לפני הטעינה.

2.ודא שהמגעים של הסוללה ושל המטען נקיים ויבשים.

20 Ð 20 צטען את הסוללה במטען מאושר.





חירור החוללה

אזהרה \Lambda

סכנת פציעה עקב קצר או נפילת סוללה!

לפני חיבור הסוללה ודא שהמגעים של הסוללה ושל המוצר נקיים מגופים זרים.

ודא חמיד ושהחוללה תפוחה הינור

.1טעו את הסוללה למצב מלא לגמרי לפני השימוש הראשוו.

.2דחף את הסוללה למוצר עד שאתה שומע אותה ננעלת.

נודא ושהחוללה יוושרת הינור

החרת החוללה

.1לחץ על לחצו השחרור של הסוללה. .2משוד את הסוללה החוצה מהמוצר.

אבטחת נפילה

אזהרה \Lambda

סכנת פציעה כשכלי העבודה ו/או האביזר נופלים!

► השתמש רק בחבל אבטחה של Hilti המומלץ עבור המוצר שלד.

בדוק את נקודת החיבור של חבל האבטחה של כלי העבודה לפני כל שימוש כדי לזהות נזקים.



שם לב לחוקים בנוגע לעבודה בגובה.

מותר לאבטח מוצר זה נגד נפילות אר ורק באמצעות שילוב של רצועת האבטחה Hilti אני 12293133 של אבטחה .Hilti של #2261970

- ► חבר את רצועת האבטחה לפתחי התקנת האביזרים. בדוק שהחיבור יציב.
- ▶ חבר שאקל אחד של חבל אבטחת כלי העבודה לרצועת האבטחה ואת השאקל השני למבנה יציב. בדוק ששני השאקלים מחוברים בצורה בטוחה.

שים לב להוראות הבטיחות של רצועת האבטחה של Hilti ושל חבל אבטחת כלי העבודה של Hilti.

כוונוו מהירות החיתוד

התאם את מהירות החיתוד בעזרת גלגל כוונוו הסל"ד.

החלפת סכין 🛛

זהירות \Lambda

סכנת פציעה! הכלי עשוי להיות חם מאוד ו/או חד.

לבש כפפות מגו בעת החלפת כלי.

לעולם איו להניח כל חם על חומרים דליקים.

זהירות \Lambda

סכנת נדק לחלק שבעבודה ולסכיו!

בחר תמיד את הסכיו המתאים לשימוש המתוכנו ולעובי החומר.



החלף את הסכין אם הוא קהה והספק החיתוך קטן. ככלל. החלף את הסכיו בהתקנה של פסי חיתור חדשים.

.1דחף את בורג המסב החוצה.

.2הוצא את הסכין במשיכה מראש החיתוך.

.5שמו קלות את בורג המסב ואת הסכיו החדש.

.4התקן את הסכין החדש.

.5דחף את בורג המסב לתור הקדח עד שהוא יינעל.





החלפת פסי חיתוך 3

זהירות 🔬

סכנת פציעה! הכלי עשוי להיות חם מאוד ו/או חד.

- ▶ לבש כפפות מגן בעת החלפת כלי.
- ♦ לעולם אין להניח כל חם על חומרים דליקים.

זהירות 🔬

סכבת בזק למוצר ולכלי החיתוך!

- ◄ לפני התקנת בורגי ההידוק נקה את התבריג.
- ▶ השתמש תמיד בבורגי ההידוק החדשים המסופקים, ושים לב למומנט ההידוק הדרוש.
- הסר את בורגי ההידוק ואת פסי החיתוך. במקרה הצורך דחף את פסי החיתוך מלמעלה באמצעות כלי עבודה מתאים. דרך ראש החיתוך.
 - .2נקה את התבריג.
 - :בדוק את פסי החיתוך:
 - ► אם רק מחצית מפסי החיתוך קהים, סובב את פסי החיתוך ב-180°.
 - אם המחצית של לפחות אחד משני פסי החיתוך קהה, החלף את שני פסי החיתוך.
 - .4התקן את פסי החיתוך ואת בורגי ההידוק.

	נתונים טכניים
5 ביוטון-מ'	מומנט הידוק

החלפת לוחית קאטר 4

זהירות 🔬

סכנת פציעה! הכלי עשוי להיות חם מאוד ו/או חד.

- ▶ לבש כפפות מגן בעת החלפת כלי.
- לעולם אין להניח כל חם על חומרים דליקים.

_____ זהירות

סכנת נזק למוצר ולכלי החיתוך!

- לפני התקנת בורגי ההידוק נקה את התבריג.
- ▶ השתמש תמיד בבורגי ההידוק החדשים המסופקים, ושים לב למומנט ההידוק הדרוש.

.1הסר את בורג ההידוק ואת לוחית הקאטר.

.2נקה את התבריג.

.8התקן לוחית קאטר חדשה והתקן את בורג ההידוק החדש.

נתונים טכניים

מומנט הידוק

תפעול

ציית להוראות הבטיחות והאזהרות שבתיעוד זה ולאלה המצוינות על המוצר.

הפעלה

.1לחץ על החלק האחורי של מתג ההפעלה/כיבוי.

.2דחף את מתג ההפעלה/כיבוי קדימה.

🕨 המנוע פועל.

.3נעל את מתג ההפעלה/כיבוי.

חיתוך 5

ודא לפני תחילת העבודה בדוק שפסי החיתוך ולוחית הקאטר מותקנים בצורה נכונה ומחודקת, ובדוק את מומנט ההידוק של בורגי ההידוק.

5 ביוטוו-מ'

1. הפעל את המוצר. 🖽 25





.2הולך את המוצר דרך החומר המיועד לחיתוך, כאשר אתה מחזיק אותו בזווית של 14° ביחס לחומר.



הקפד להשתמש בסכין חד, וסובב או החלף את פסי החיתוך בזמן.

[|] מרח שמן חיתוך או חומר קירור אחר על החלק שבעבודה, כדי להאריך את משך החיים של כלי החיתוך.

:כאשר התנאי הבא מתמלא, בצע גם את הפעולה הזו:

תנאים: חיתוך רדיוסים

רעבר את המוצר באטיות דרך החומר, ברדיוס המתאים. ◄

אל תטה את המוצר הצידה.

4.כדי לסיים את החיתוך, כבה את המוצר.

הפרדת השבבים 6

אל תפריד שבבים קצרים. האורך המינימלי של השבב צריך להיות סיבוב אחד. באזור הקדמי של גוף המכשיר קיימים סימונים שמציינים את מצב החיתוך.

.1כאשר המוצר מופעל, לחץ למשך 0.5 שניות על מפריד השבבים.

השבב יופרד עד לגובה הסימון, ותהליך החיתוך ייעצר מעצמו.

.2הסר את השבב באופן ידני.

כיבוי

- ▶ לחץ על החלק האחורי של מתג ההפעלה/כיבוי.
- ▶ מתג ההפעלה/כיבוי קופץ למיקום כיבוי והמנוע כבה.

טיפול ותחזוקה

אזהרה \Lambda

סכנת פציעה כאשר הסוללה מחוברת !

▶ לפני ביצוע עבודות טיפול ותחזוקה כלשהן יש להקפיד להסיר את הסוללה!

טיפול במוצר

- הסר בזהירות לכלוך דבוק.
- אם ישנם, נקה את חריצי האוורור בזהירות בעזרת מברשת רכה ויבשה.
- נקה את גוף המכשיר רק באמצעות מטלית לחה מעט. אל תשתמש בחומרי טיפול המכילים סיליקון, מאחר שהם עלולים לפגוע בחלקי הפלסטיק.
 - נקה את המגעים באמצעות מטלית נקייה ויבשה.

טיפול בסוללות ליתיום-יון

- לעולם אין להשתמש בסוללה שחריצי האוורור שלה סתומים. נקה את חריצי האוורור בזהירות בעזרת מברשת רכה ויבשה.
- מנע חשיפת הסוללה לאבק ולכלוך שלא לצורך. בשום אופן אין לחשוף את הסוללה ללחות גבוהה (לדוגמה להטביל אותה במים או להניח אותה בגשם).

אם הסוללה נרטבה מאוד, יש להתייחס אליה כאל סוללה פגומה. בודד אותה במיכל לא דליק ופנה לשירות של Hilti.

 שמור על הסוללה בקייה משמן וגריד לא שייכים. אל תאפשר הצטברות מיותרת של לכלוך ואבק על הסוללה. בקה את הסוללה במטלית יבשה ורכה או במטלית נקייה ויבשה. אל תשתמש בחומרי טיפול המכילים סיליקון, מאחר שהם עלולים לפגוע בחלקי הפלסטיק.

אל תיגע במגעים של הסוללה ואל תסיר מהמגעים גריז שהושם במפעל.

 נקה את גוף המכשיר רק באמצעות מטלית לחה מעט. אל תשתמש בחומרי טיפול המכילים סיליקון, מאחר שהם עלולים לפגוע בחלקי הפלסטיק.

תחזוקה

- בדוק באופן סדיר את כל החלקים הגלויים כדי לאתר נזקים ולוודא שכל הרכיבים פועלים באופן תקין.
 - אל תפעיל את המוצר אם ישנם נדקים ו/או תקלות. פנה מיד לשירות של Hilti כדי לתקן את המוצר.
- לאחר עבודות טיפול ותחזוקה יש להתקין בחזרה את כל ציוד ההגנה ולבדוק שהוא פועל בצורה תקינה.





לצורך הפעלה בטוחה של המכשיר יש להשתמש רק בחלקי חילוף וחומרים מתכלים מקוריים. את חלקי החילוף, החומרים המתכלים והאביזרים שאושרו על-ידי Hilti עבור המוצר שלך תמצא ב-Hilti Store שלך או בכתובת: www.hilti.group

הובלה ואחסון של כלי עבודה נטענים וסוללות הובלה

זהירות 🔬

התחלת פעולה בשוגג במהלך הובלה !

- יש להוביל את המכשיר כשהסוללה מנותקת ממנו!
 - א הוצא את הסוללה/ות.
- ► לעולם אין להוביל את הסוללה בצורה חופשית בין עצמים לא ארוזים. בזמן ההובלה הסוללות צריכות להיות מוגנות מפני חבטות ורעידות רבות וכן מבודדות מפני חומרים מוליכים כלשהם או סוללות אחרות, כדי שלא ייווצר מגע בינן לבין מגעים של סוללות אחרות ועקב כך קצר. שים לב לכללי ההובלה במדינתך בנוגע לסוללות.
 - ▶ אסור לשלוח סוללות בדואר. אם אתה רוצה לשלוח סוללות לא פגומות, פנה לשם כך לחברת משלוחים והובלות.
 - ◄ בדוק אם ישנם נזקים במוצר ובסוללות לפני כל שימוש וכן לפני הובלה ארוכה.

אחסון

אזהרה \Lambda

בזק לא מכוון כשהסוללות פגומות או דולפות !

- יש לאחסן את המכשיר כשהסוללה מנותקת ממנו!
- ▶ אחסן את המוצר והסוללות במקום קריר ויבש. שים לב לערכי הגבול של הטמפרטורה, כמצוין בנתונים הטכניים.
 - אין לאחסן סוללות על המטען. הקפד להוציא את הסוללה מהמטען בסיום תהליך הטעינה. ◄
 - ◄ לעולם אין לאחסן סוללות בשמש, על מקורות חום או מאחורי זכוכית.
 - ▶ אחסן את המוצר והסוללה הרחק מהישג ידם של ילדים או אנשים לא מורשים.
 - ▶ בדוק אם ישנם נזקים במוצר ובסוללות לפני כל שימוש וכן לפני אחסון ממושך.

תיקון תקלות

בכל תקלה שים לב לחיווי המצב של הסוללה. ראה הפרק **תצוגות של סוללת הליתיום-יון**.

אם מתרחשת תקלה שאינה מוסברת בטבלה זה או שאינך יכול לתקן בעצמך, פנה לשירות של Hilti.

פתרון	סיבה אפשרית	תקלה
 אפשר לסוללה להתחמם בהדרגה לטמפרטורת החדר. 	טמפרטורת סביבה נמוכה מאוד.	הסוללה מתרוקנת מהר מהרגיל.
◄ נקה את זיז הנעילה וחבר את הסוללה מחדש.	זיז הנעילה בסוללה מלוכלך.	הסוללה אינה נתפסת בצליל "קליק" ברור.
◄ כבה מיד את המוצר, הוצא את הסוללה, השגח עליה, אפשר לה להתקרר וצור קשר עם השירות של Hilti.	תקלה חשמלית	התחממות גבוהה במוצר או בסוללה.
החלף סוללה, וטען את הסוללה הריקה.	הסוללה התרוקנה.	אין בלימת מנוע.
 כבה את המוצר והדלק אותו מחדש. 	עומס יתר זמני על המוצר.	
► השתמש בסוללה בעלת קיבולת מספיקה.	חוברה סוללה בעלת קיבולת נמוכה מדי.	המוצר אינו פועל בעוצמה מלאה.
🕨 החלף את הסכין. 🖵 24	הסכין ו/או פסי החיתוך קהים מדי.	ירידה בהספק החיתוך
🕨 החלף את פסי החיתוך. 🖾 25		
פנה למעבדת שירות של Hilti.	הסוללה פגומה.	נוריות הסוללה אינן מציגות דבר





סילוק

אזהרה 🧄

סכנת פציעה בעקבות סילוק לא תקין! סכנה בריאותית מהשתחררות גזים ונוזלים.

אין לשלוח סוללות פגומות! ◄

. כסה את החיבורים באמצעות חומר לא מוליך, כדי למנוע קצר

▶ סלק סוללות כך שהן לא יוכלו להגיע לידיהם של ילדים.

► סלק את הסוללה ב-Hilti Store או פנה לחברת המיחזור האחראית.

או המוצרים של Hilti מיוצרים בחלקם הגדול מחומרים ניתנים למיחזור. כדי שניתן יהיה למחזרם דרושה הפרדת חומרים hilti מיוצרים Hilti מיוצרים או שלים מקצועית. במדינות רבו Hilti היק למשווק.

אין להשליך כלי עבודה חשמליים, כלים אלקטרוניים וסוללות לפסולת הביתית! 🔹

אחריות יצרן

אם יש לך שאלות בנושא תנאי האחריות, אנא פנה למשווק Hilti הקרוב אליך.

מידע נוסף

מידע נוסף על ההפעלה, הטכנולוגיה, הגנת הסביבה ומיחזור תמצא בקישור הבא: ar.hilti.com/manual/?id=2327536&id=2332250

קישור זה מופיע גם כקוד QR בהוראות ההפעלה האלה, מסומן בסמל 🚯.









ų,

B 22-55 (01)	0,56 kg	1.23 lb
B 22-85 (01)	0,77 kg	1.70 lb
B 22-110 (01)	0,92 kg	2.03 lb
B 22-170 (01)	1,34 kg	2.95 lb
B 22-255 (01)	1,87 kg	4.12 lb

.,	
C 4-22	
C 6-22	
C 8-22	







CE

Declaration of conformity

Declaration of conformity

The manufacturer declares, on his sole responsibility, that the product described here complies with the applicable legislation and standards.

The technical documentation is filed here:

Hilti Entwicklungsgesellschaft mbH | Tool Certification | Hiltistrasse 6 | D-86916 Kaufering, Germany Product information

Slitting shear	SSH 6-22
Generation	02
Serial no.	1-99999999999





הצהרת תאימות

הצהרת תאימות

היצרן מצהיר באחריותו הבלעדית כי המוצר המתואר כאן עונה על דרישות החוק התקפות והתקנים התקפים. התיעוד הטכני שמור כאן:

Hilti Entwicklungsgesellschaft mbH | Zulassung Geräte | Hiltistraße 6 | 86916 Kaufering, Germany נתוני המוצר

SSH 6-22	מספרי חריץ
02	דור
999999999999-1	מס' סידורי



EN 62841-1:2015, AC:2015, A11:2022 EN 62841-2-8:2016 EN IEC 55014-1:2021 EN IEC 55014-2:2021

2014/30/EU 2011/65/EU

Hilti Corporation Feldkircherstraße 100 9494 Schaan | Liechtenstein SSH 6-22 (02) 2006/42/EC

Schaan, 29.03.2024

H

Dr. Tahar Zrilli Head of Quality and Process Management Business Area Electric Tools & Accessories

ELIZP.

Edward-Louis Przybylowicz Head of BU Power Tool & Accessories Business Area Electric Tools & Accessories





UK

UK Declaration of Conformity

Declaration of conformity

The manufacturer declares, on his sole responsibility, that the product described here complies with the applicable legislation and standards.

The technical documentation is filed here:

Hilti Entwicklungsgesellschaft mbH | Tool Certification | Hiltistrasse 6 | D-86916 Kaufering, Germany Product information

Slitting shear	SSH 6-22
Generation	02
Serial no.	1-999999999999

Manufacturer:	UK Importer:
Hilti Corporation	Hilti (Gt. Britain) Limited
Feldkircherstraße 100	No. 1 Circle Square, 3 Symphony Park
9494 Schaan Liechtenstein	Manchester, England, M1 7FS
SSH 6-22 (02)	



Supply of Machinery (Safety) Regulations 2008 Electromagnetic Compatibility Regulations 2016 The Restriction of the Use of Certain Hazardous Substances in Electrical and Electronic Equipment Regulations 2012 EN IEC 55014-2:2021

EN 62841-1:2015, AC:2015, A11:2022 EN 62841-2-8:2016 EN IEC 55014-1:2021

Schaan, 29.03.2024

aba

Dr. Tahar Zrilli Head of Quality and Process Management Business Area Electric Tools & Accessories

ELIST

Edward-Louis Przybylowicz Head of BU Power Tool & Accessories Business Area Electric Tools & Accessories





Hilti Corporation LI-9494 Schaan Tel.:+423 234 21 11 Fax:+423 234 29 65 www.hilti.group





Hilti = registered trademark of Hilti Corp., Schaan

Pos. 1 | 20240821